

REPORT of SURVEY for REPAIRS, &c.

now Enr. S.

(Received at London Office)

15 JAN 1936

No. 23561.

Date of writing Report 14 Jan 1936 When handed in at Local office 14 JAN 1936 Port of NEWPORT, MON.

in Survey held at NEWPORT, MON.

on the Wood, Iron or Steel SS. "YOSERIC."

175 TONNAGE

GROSS 5240

UNDER DL 1790

1721

Built at Sunderland By whom Sir J. Lain & Sons, Ltd. When 1918. YEAR 7.

Owners Bank Line, Ltd.

Managers G. Wm & Co.

Owners' Address ✓
(if not already recorded in Appendix to Register Book).

Port belonging to Glasgow.

Surveyed Afloat or in Dry Dock? Afloat Name of Dock River Mersey.

Destined Voyage

FB=Cell D/B or DBa feet; uE&B feet; f feet
Capacity tons. FPT tons; APT tons; MT feet tons.

N.B. All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

First Report, No. 7445 Port H.Kg

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; a list being detailed in the body of the report, should be summarised in the form shown below. Whenever the statement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case. H. 6/1936

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? If so, by whom?

AIRS. OR EXAMINATION AS PER RULE, FOR Absentment of 2nd Special Survey, 17.1.

Vessel lying afloat, now laid up. (See also Ship Report.)
Examined, 17.1.2.3 Hold and Tween decks, C. B. spaces + under
Boilers, Bridge space bunks forward of 1.3. Hatch, and
Port + Star. Pooplet bunkers.

Examined, 1.1.3 double bottom tanks and fore + after peak tanks
internally, also air + sounding pipes.

Poop space examined, and all found or to be put in good
condition. All the above steel work requires to be thoroughly
scaled + coated. Lumber lifted for cleaning of bilges.

ART OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Removed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PT CONDITION OF THE	1	State if Tanks have been examined inside 1.2.3	1.2.3	Air and Sounding Pipes	see Rpt	Copper, or Y.M. of Wood Vessels	
		State if Tanks now tested	no	Dblng. Plates under Sounding Pipes	1.2.3. Good	(State if on Pelt).	
		Bulkheads	see Rpt	Engine Room Skylights		When put on, Month	Year
		Ceiling	.	Coal Bunkers, Open'gs, Lids, &c.	see Rpt	Boats	
		Cement or Asphalt (State which.)	ceament	Oil Bunkers		Masts, Yards, &c.	
		Rudder	✓	Scuppers		Condition, how ascertained	
		Steering gear and its connections	✓	Cargo Hatchways	see Rpt	(State if wedges removed)	
		Windlass	✓	Hatches		Sails	
		Have Pumps now been examined and found effi- cient?	✓	Planking	of Wood Vessels	Equipment letter	4
		Have Sluice Valves now been examined and found efficient?	✓	Caulking	ditto	Anchors, No. of	10
		Have Watertight Doors now been examined and found efficient?	✓	Treenails	ditto	Cables (State if now ranged)	
		Have Ventilators and their Comings been examined and found efficient?	✓	Breasthooks & Stemson	ditto	" length	mean diamr.
		see Rpt		Transoms, Pointers, & Crutches	ditto	" (on board)	
		see Rpt		Timbers of Frames at openings	ditto	" Rule length.	size
		see Rpt		Stringers, Clamps & Shelves	ditto	Hawser & Warps	
		Salting		(State if examined.)		Standing and Running Rigging	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"..... to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24 and ptnd24, &c."

This vessel so far as now seen is eligible in my opinion to remain as classed without fresh Record of Survey and to have notation of S.S. 1.1. - with date, when the survey has been completed and repair carried out. Read M. Pier to specify examin and dredging also (including plating, painting, &c.)

2 (per Section 29) £ : :

Fees applied for,

19

Damage or Repair Fee (if any) £ : :

Received by me,

19

Expenses (if chargeable) £ : :

19

Surveyor's Fee (if any) £ : :

19

Committee's Minute

FRI. 31 JAN 1936

Character Assigned

Deferred for
Comp. No. 1

W.Hayman

Surveyor to Lloyd's Register of Shipping

FRI. 13 MAR 1936

FRI. 7 AUG 1936

Deferred

With own

NH (copy)

W.L. 1936

15 JAN 1936

on the

S.S. YOSERIC

For Peak Taust. - 6 main frames to repair by fitting brackets above & below lower stringer.

1:6 floor to rivet to main frame

1:7 frames to partly riveted.

Cement box on way of 1:1 frame to cut away, rivets dealt with.

Four (bulb head) brackets, plates, angles to renew.

1:1 D. B. Taust, S. S. - 25 tank side floor angles to renew.

Floor, 1:2 to 14 doublng plates to fit at top of margin plate when fractured.

- P.S. - 23 tank side floor angles to renew

Floor 1:6 to 14 doublng plates to fit at top of margin plate when fractured.

1:1 Hold. star Side. - Solid Cement in 1:3+4 bilge pockets to cut out for examination of plating.

1:12. Web. frames (fractured) to be repaired.

Lower section of 1:2 web. frames to be renewed

Beam sheer in way of the above to rivet
24 tank side brackets to renew with tank top tie angles.

Port. Side. - 1:2 web frame (fractured) to be repaired and beam sheer in way riveted.

Forward stringer plate and bulbhead bracket to renew.

26 Tank side brackets to renew with tank top tie angles.

1:1. Thunderd. - Doubling plates to fit for full breadth at bottom of For Peak bulkhead.

all hatch covers to make good, forward & after rest angles to fair in plan, 6 athwartship beam rest angles to fair, Beam ends to rivet, shores to fair. 20 hatch cleats to renew.

1:1. Main Deck. Hatch. - all hatch covers to renew


6 athwartship beams to repair.

Hatch battens to renew.

1:2 D. B. tank. - Taust end between 1:2 + 3 tanks to double on star side.

1:2 hold. - 32 reverse angles to fit top of tank side brackets Port & star.

© 2019



Lloyd's Register
Foundation
W479-O3151215)

Port of NEWPORT, MON.

Continuation of Report No. 23561 dated 14 JAN 1936

on the

S.S. YOSERIC

11:2 Fore Hold. - 16 Tank top tie angles 10 renew. Port. 1 slm"

11:2 Tween. Deck. - Hatch Cover 10 make good, 6 athwartship beams 10 repair.

11:3 Main Deck. - 16 Hatch cleats 10 renew, Horizontal stiffens on Hatch covering P. Side 10 renew.

6 athwartship beams 10 upon. 13 angle shores 10 fair.

11:3 Fore Hold. - Port. 1 slm" bulkhead renew, bottom plate 10 renew
Stockhold falsehood 10 crop & port renew of wing
11 tanksides brackets 10 renew on slm sills.
6 reverse angles 10 fit on top of Tank side brackets
8 Tank top gusset angles 10 renew11:3 Bridge T. Deck. - Cambi fore & aft 10 renew, sides fore & aft beam 10 fair. Hatch cover (wood) 10 renew
12 Hatch cleats 10 renew. Batten top 10 renew11:3 Main Deck (B. space) - Hatch Cover 10 renew, 3 F. A. Hatch beams 10 renew, 6 shores 10 renew
Double plating on deck round Hatch end & corners 10 renew
1 deck stringer plate P. & S 10 renew, ahead Hatch.
2 Ventilation Tubes 10 renew.

Side Bulkhead. - 8 tank side brackets. 4 tank top gusset angles 10 renew.

11:4 Fore Hold P.P. - 10 Tank side brackets 10 renew, 16 reverse angles 10 fit on tops of Tank side brackets.

Double plating 10 fit aft falsehood at bottom.

• • • S.S. - 15 tank side brackets 10 renew, 12 reverse angles on tops of Tank brackets 10 fit.

12 Tank top gusset angles 10 renew.

Double plating 10 fit on falsehood at bottom.

11:4 Tween Deck. - 6 athwartship beams 10 fair, Hatch Cover 10 make good, 20 Hatch cleats 10 renew.

Deck in way of steering engine 10 double

11:4 Main Deck - 6 Hatch beams 10 repair, Hatch Cover 10 renew
Horizontal stiffens on Hatch P. Side 10 renew. 34 cleats 10 renew

© 2019

Lloyd's Register
Foundation

SS "YOSERIC".

11:05. Lower Hold P.S. - 9 Tand side brackets to renew, 8 reverse angles to fit on Tand side brackets.

15 Tand top gasket angles to renew.

Doubling plate to fit on Tand top at for' end.

8:30. - 15 Tand side brackets to renew, 5 reverse angles to fit at top Tand side brackets, 1 Tand top gasket angle to renew.

1 doubling plate to fit on Tand top at for' end.

Tand end in way of well to be doubled or part renewed.

11:05. Tand Deck - Hatch beams to repair, 20 Hatch cleats to renew. Hatch cover to make good.
2 Ventilation Tubes to renew.

11:05 Main Deck. - Hatch beams to repair, 36 Hatch cleats to renew. Batten bars to renew. 11 horizontal bulk angles stiffen on Hatch P. Side to renew.
Hatch Cover to renew.

Cargo Room. - Main engines and pumps to lift and tank top plating, floor + intercostals to be dealt with.

Poop. Deck. - 5 deck plates to renew and 3 deck plates to double.

Buoy Deck. - 3/4" for' tanks Hatch deck to renew + coamings to rivet. 3 beams to repair. (claim) 12 Hatch cleats to renew
3/4" aft tanks Hatch, 3 main beams in way to repair, 12 cleats to renew.
Port. for' tank Hatch, Hatch coaming to renew with fittings. 3 main beams in way to repair.

Forec't Deck. - Port Hawse Pipes + deck flangs to renew star" " " deck flangs. to repair.

Fore Well. Deck. - Bulwark plates when fractured to have doubling plates fitted.

Sheepplating. - 11:2, 5 Holds. Cement bases to be cut away in way of fractured sheepplating on Port side and sheepplating to be renewed or doubled.

15 JAN 1936

on the

SS. "YOSERIC"

a number of ventilator cowls to remove.
 all air & sounding pipes to make good
 all steel work to be thoroughly sealed & coated.
 for further repair etc see attached specification.

To complete S.S. 2nd M^o. The following remain to be done.

Vessel to place in dry dock. Bottom, Rudd 10 exams

Cathes 10 raves, anchors, cables, Cables 10 exams.

steering engine, Pumps & N.T. doors, 10 exams.

sheathing in way of sidelights 10 exams

Ceilings on tank tops 10 removal as required.

Fore & aft peak tanks 10 feet.

all double bottom tanks to test except 17.4 Tons.

all steel work to be sealed & coated, additional repair to the above may be required after sealing.

The owners state that the survey will be completed before vessel sails from this port.

Subord to verify. General Equipment 6 exams OK

RETAIN



© 2019

Lloyd's Register
Foundation

W 49-095 (515)