

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office DEC 1 1939)

Date of writing Report 20. 10. 1939 When handed in at Local Office 20. 10. 1939 Port of Bombay
 Date, First Survey 12. 9. 39 Last Survey 14. 10. 1939
 Survey held at Bombay (No. of Visits 8)
 on the Machinery of the T.S.S. "JUNA"
 Gross 2190 Vessel built at Newcastle By whom Swan, Hunter & Wigham Richardson When 1927-6
 Net 905 Engines made at Newcastle By whom Swan, Hunter & Wigham Richardson When 1927
 Indicated Horse Power 469 Boilers, when made (Main) (Donkey)
 of Main Boilers 3 Owners British India S.N. Co., Owners' Address Government
 of Donkey Boilers 3 Managers and Port London Voyage Service
 Main Boilers 215 lbs Surveyed Afloat or in Dry Dock Hughes Drydock
 Donkey Boilers ✓ (State name of Dock.)

Particulars of Examination and Repairs (if any) L.M.C
 Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.
 Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓
 Was a damage report made by anyone else? If so, by whom? ✓
 Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.
 " " Donkey " " " " ✓
 Was this not done, state for what reasons? ✓
 What parts of the Boilers could not be thus thoroughly examined? ✓
 What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓
 Latest date of internal examination of each boiler 18/9, 19/9 + 27/9/39

CHARACTER for Special Survey Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., if any)
<u>100A1-9'38</u> <u>With fuel tank</u> <u>S.S. Cal. No. 2-'35</u>	<u>LMC-9'35</u> <u>BS-9'38</u> <u>TSCL-PN. 9'36</u> <u>S 9'38</u>
<u>FITTED FOR OIL FUEL 6.27</u> <u>F.P. ABOVE 100PS.</u>	

Present condition of funnel(s) Good.
 To what pressure were they afterwards adjusted under steam? 215 lbs □ "
 Did the Surveyor examine the Safety Valves of the Main Boiler? Yes. To what pressure were they afterwards adjusted under steam? ✓
 Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓
 Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boilers? ✓
 Did the Surveyor examine the drain plugs of the Main Boilers? Not examined and of the Donkey Boilers? ✓
 Did the Surveyor examine all the mountings of the Main Boilers? Yes. and of the Donkey Boilers? ✓
 Has the screw shaft now been drawn and examined? Part only Is it fitted with continuous liner? Yes. Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓
 Has the shaft now been changed? No If so, state reasons ✓
 Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓
 Date of examination of Screw Shaft 27/9/39 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft S = 5/32"
 Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted? Yes.
 Did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes.
 Was the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

Vessel in drydock. Examined propellers, stern bush ends & outside sternwings & found all in efficient condition. Port screw shaft (cl) drawn in & found in efficient condition. Bush unwooded. Cylinders, pistons & valves; cranks thrust & intermediate shafting, condensers pumps & their connections of both engines; the sea, bilge & overboard discharge valves & their connections & the auxiliaries & their connections opened up & examined throughout. Found or made good. Condensers tested & made tight. The electrical installation examined throughout and tested in accordance with the Rules & wiring & connections made good P.T.O.

General Observations, Opinion, and Recommendation:—The machinery of this vessel (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, E.S.M.S. 9,11, & L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.) is in efficient condition & is eligible in my opinion to remain so classed with fresh records of LMC-10,39 & T.S. p.(cl) 7,39.

Fee (per Section 29) Rs 480/-
 Special Damage or Repair Fee (if any) Rs 48/-
 Survey fee - Rs 48/-
 Calling expenses (if chargeable) Rs 15/-
 Fees applied for 20. 9. 1939
 Received by me, 19

Committee's Minute TUE 12 DEC 1939
 Signed + Lamb 10.29

H. Southwell & J. Bailey
 Engineer Surveyor to Lloyd's Register of Shipping.



CERTIFICATE WRITTEN

W48-0139

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

2."Juna"

as found necessary.

The 3 main boilers examined throughout with mountings & found in efficient condition. The steam pipes examined and tested in accordance with the Rules. Mountings overhauled. Boilers afterwards examined under steam & safety valves adjusted as above.

Repairs.

Ballast pump distribution valve box renewed, & a new pump bucket fitted. Remaining machinery generally overhauled & adjusted & minor repairs effected.

H. P. Southwell

E. Oxley (per H.P.S.)

Sp3 held.

Minor repairs

It is submitted that
this vessel is eligible for
THE RECORD.

Value 10 39
Cost 9 39

W
Belkiss

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page]



© 2020

Lloyd's Register
Foundation