

Report of Survey for Repairs, &c., of Engines and Boilers.

16 MAR 1936

(Received at London Office)

Report 24th Feb. 1936. When handed in at Local Office 19 Port of PORT NATAL
Survey held at PORT NATAL Date, First Survey 6th Feb. Last Survey 22nd Feb. 1936 (No. of Visits 8)
the Machinery of the ~~Steel~~ SC. "NORDLAND"
6559 Vessel built at Kinghorn By whom Kinghorn S.B. Co. When 1921-5
2996 Engines made at Glasgow By whom G. Henderson & Co. Ltd. When 1921
278 Boilers, when made (Main) 1921 (Donkey)
3 Owners Rederei Nordmark A/S Owners' Address
Managers (if not already recorded in Appendix to Register Book.)
Port Hamburg Voyage Mogadiscio
If Surveyed Afloat or in Dry Dock Yes. (State name of Dock.)
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. for Special Survey Date of last Survey and of Periodical Surveys.	Year assigned now expired.	Machinery and Boiler Surveys (including date of N.B. if any).
+100.A.1.		+L.M.C. 12.33.
11.34.		B.S. 6.35.
S.S.HAM. N°3-12.33		S.2.33.C.L.

No. Port
of Examination and Repairs (if any) Damage

when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on the cause of which must be stated should be separated from Repairs due to other causes; and the nature of the repairs should be briefly summarised at the end of the report. State also the nature of any letters respecting this case.

where the Surveyor has not made a special damage report he is required to state whether he has advised the owner of the vessel of the nature of the damage and why they were declined

port made by anyone else? If so, by whom?

personally go inside Main Boiler separately and make a thorough examination at this time? Yes

Donkey " " "

state for what reasons?

the Boilers could not be thus thoroughly examined?

means, in the absence of internal examination, were adopted by the
himself of the thorough efficiency of those parts of each Boiler?

internal examination of each boiler Centre Bhr. 18/2/36

examine the Safety Valves of the Main Boiler? Yes

To what pressure were they afterwards adjusted under steam? 200 lb/sq.

examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

examine all the manholes, doors and their fastenings of the Main Boilers? Yes

, and of the Donkey Boilers?

examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

examine all the mountings of the Main Boilers? Yes

, and of the Donkey Boiler?

been drawn and examined? Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

changed? If so, state reasons

been previously used? Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

tion of Screw Shaft. State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

complete, state what arrangements have been made for its completion and what remains to be done Complete.

age, stated to have been sustained on the 5th February 1936. Examination at this port 16/ tubes of the Centre Boiler were found to be badly distorted and overheated.

was recommended that all the distorted tubes be cut out and replaced, and all leaking tubes expanded.

was further recommended that the mountings of the Centre Boiler be opened up for examination and all the boilers be opened up, cleaned and examined.

on completion of the above repairs, the Centre Boiler was tested under pressure to 235 lb/sq. and subsequently under steam with satisfactory results.

Observations, Opinion, and Recommendation:— The machinery of this vessel

what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also the nature of the repairs required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.S. 9,11, & L.M.C. 9,11, or 140 lb., F.D., &c.)

is eligible in my opinion to remain as classed, at fresh record by survey.

or Repair Fee (if any) £ 18: 15: 0
Fees applied for 21/2/1936
Received by me, 19

ee's Minute FRI. 27 MAR 1936

FRI. 12 JUN 1936

For T. G. McClung & Co.

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W482-0019