

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report	25-1-1932	When handed in at Local Office	(Received at London Office)
No. in Reg. Book.	Survey held at Schiedam		
Tonnage	Gross 6559	Net 3996	Date, First Survey
Nominal Power	678	of Main Boilers	1921
Donkey Boilers	100	Managers	Hamburg
Pressure		If Surveyed Afloat or in Dry Dock	Hamburg Voyage
Main Boilers	100	(State name of Dock.)	Wilton's
Donkey Boilers			

Report No. Port

Particulars of Examination and Repairs (if any) Damage

Special Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the extent of damage (the cause of which must be stated) should be separated from Repairs due to other causes; and initials of any letters respecting this case.

Cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Yes, not required

Damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey "

Was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor examine the Safety Valves of the Main Boiler?

Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

To what pressure were they afterwards adjusted under steam?

Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated?

Shaft now been changed? If so, state reasons

Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated?

Shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated?

Distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

a fit

Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Complete

This vessel is reported to have been aground in the Vulcaanhaven on the 24th of October 1931.

Scrub placed in dry dock, screw shaft drawn, examined and found good. Bellcrank, one blade bent at tip, some now fairied and found good. Reconnections and fastenings examined and good. Thrust and tunnel shafting examined and found in order.

General Observations, Opinion, and Recommendation: — *The machinery being now to clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c., thus, for example, B.S. 9/11, I.M.M.S. 9/11, or + L.M.C. 9/11, 140 ft., F.D., &c.)*

far as seen in a good condition I am of opinion that the vessel is able to remain as classed and notation of T.S. seen 1-32.

Fee (per Section 29) £ : : Fees applied for 19
Actual Damage or Repair Fee (if any) £ 60.00
(per Section 29.) £ 2.00 Received by me, 12/2/1932
Filing expenses (if chargeable) £ 2.00
Committee's Minute TUE. 9 FEB. 1932

Engineer Surveyor to Lloyd's Register of Shipping.

Is a Certificate required? If so, to be sent to

as now, without spl. condn.
S.1-32.

