

Belongs to Rott. Rep N 14506
Recd 7/9/25

of ROTTERDAM.

5th September, 1925.

Leendert Vuijk,

the Owners Representative hold a survey on board of the Norwegian steel screw steamer "KINGORN" 6596 tons gross, on the 14th of August 1925 and on subsequent dates, whilst placed in Wilton's Drydock at Schiedam, in order to ascertain the nature and extent of the damage alleged to have been sustained through the following causes:

- 1°. Grounding whilst passing through the Suez Canal and again whilst lying at anchor in the Canal near Port Said on the 12th of April 1925, on a voyage from Melbourne to Marseille and Genoa;
- 2°. Collision with the s.s. "Monte Neveso", at Genoa on the 30th of April 1925;
- 3°. Grounding near the Sun Shipbuilding yard at Philadelphia on the 27th of June 1925;
- 4°. Touching the ground near the Delaware River Steel Co's Wharf at Philadelphia on the 1st of July 1925.-

For further particulars see Logbook.-

P o u n d:

A number of local rivets in shell started, principally in bilge strake.

One rivet in lower scarp of rudderpost started.

R e c o m m e n d e d:

Twenty four rivets on port and seven rivets on starboard to be renewed.

To be renewed.



© 2019

Lloyd's Register
Foundation

S.S. "KINGHORN".

- 2 -

5/9/25.

Three butt-traps of starboard
bulge strake started and leaking.

To be recaulked.
Double bottom tanks to be
drained in dock and opened
out for repairs.

No. 1 Hold. Three lugs to tank-
top and frame brackets started
and leaking.

To be recaulked.
No. 1 Double bottom tank to
be tested upon completion.

No. 2 Hold. One lug to tanktop
and frame bracket fractured.

To be renewed.
No. 2 Double bottom tank to
be tested upon completion.

Lead suction pipe to starboard
well damaged and broken.

To be renewed.

No. 4 Hold. A number of rivets
in top of deeptank started.

To be renewed.
Deeptank to be tested upon
completion.

No. 5 Hold. Five lugs to tank-
top and frame brackets starboard
and seven lugs port fractured.

To be renewed.

A number of rivets in deck top on
portside started.

To be renewed.
No. 6 Double bottom tank to
be tested upon completion.

One rivet in afterdeeptank
bulkhead started.

To be renewed.

Six tarpauling damaged.

To be repaired and made good.

Railing damaged on portside
midships and aft and on star-
boardside forward and aft.

To be recaulked and payed.

Wood decks in way of chartroom
and wheelhouse started and leaking.

To be repaired and made water-
tight.

Hawse pipe connections leaking

To be renewed.

Bolts and packing of rudder
stuffing box damaged.

Bottom and rudder and all
repaired work to be recadeted.

The above repairs have been carried out as recommended and have
been duly reported to Lloyds Register Office, London.

Fees f. 150.00

Expenses . . . f. 4.00

Chayh



© 2019

Lloyd's Register
Foundation