

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 10 Feb 1923 When handed in at Local Office 19 Port of Rotterdam

No. in Survey held at Rotterdam Date, First Survey 22 Dec 1922 Last Survey 9 Feb 1923
Reg. Book. 64311 on the Wood, Iron or Steel 5 1/2" KINGHORN Master (No. of Visits 20)

TONNAGE: - Built at Kinghorn By whom Kinghorn S.B.C When 1921 5
GROSS 6505 Owners L. Christiansen (Mol) Port belonging to Bergen
UNDER DK. 456 Owners' Address Bergen
NET 2990 (if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock? both Name of Dock Wiltons Dock Destined Voyage not decided

WB=CellDBorDBa feet; uE&B feet; f feet; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements),
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 3362 Port Blt.

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys. Years Assigned and Surveyed. Machinery and Boiler Surveys (including date of N.B., if any).

100 A1 11.22 Shell deck with pulrow
LMC 9.21 B.S. 11.22
CL.
W.T.B.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? *Yes not required* Was a damage report made by anyone else? If so, by whom? *✓*

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Survey of damage repairs*

1 The vessel is reported to have struck a submerged object on the 15th of November 1922 on her voyage from New York to Baltimore;
2 grounded in the Channel Hampton Road (Lamberts Point Norfolk) on the 1st of December 1922
sustained damage through heavy weather from the 4th till the 10th of December 1922 on her voyage from Baltimore to Rotterdam and sustained damage through collision with the 55 Misty Law (ex Lunderdyk) on the river Haas on the 28th of December 1922.

Please see continuation sheet.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed	0			3	3	1		upper part stem frame
Removed and Faired or Repaired	3	4						
Faired or Repaired in place	2							

PRESENT CONDITION OF THE		State if Tanks have been examined inside		Dblng. Plates under Sounding Pipes		Copper, or Y.M. of Wood Vessels	
Decks	good	yes	yes	not end	not end	(State if on Felt.)	When put on, Month Year
Caulking of Decks	"	yes	yes	good	good		
Waterways	"	good	good	"	"	Boats	good
Coamings	"	"	"	"	"	Masts, Yards, &c.	not end
Beams & Fastenings	as far as end	"	"	"	"	Condition, how ascertained	"
Outside Plating	"	"	"	"	"	(State if wedges removed)	no
Caulking of ditto	"	"	"	"	"	Sails	AT
Rivets	"	"	"	"	"	Equipment letter	Complete
Breasthooks & Crutches	not end	"	"	"	"	Anchors, No. of	Complete
Transoms	good	"	"	"	"	Cables (state if now ranged)	no
Frames	"	"	"	"	"	" length (on board)	size
Reverse Frames	"	"	"	"	"	" Rule length	size
Floors	"	"	"	"	"	Hawser & Warps	sufficed
Keelsons	"	"	"	"	"	Standing & Running Rigging	good
Stringers	"	"	"	"	"		
Inner Bottom Plating	"	"	"	"	"		

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptnd15, &c."

The vessel is now in a good and efficient condition and eligible in our opinion to be continued as classed with fresh record of Survey 2-23—

Survey Fee (per Section 28) £ : : Fees applied for, 9/6 1923
Special Damage or Repair Fee (if any) £ 400.00 : : Received by me, 9/6 1923
Travelling Expenses (if chargeable) £ 6.00 : :
Second Surveyor's Fee (if any) £ : :
Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI. 23 FEB. 1923

Character Assigned Hull Certificate Written 10001 Shell dk with pld.

S. S. KINGHORN

Grounding damage.

The vessel has been placed in dry dock Bottom and rudder cleaned, examined, and found top part of Cast steel stern-frame fractured. A new top part of Stern frame (Cast steel and marked LLOYDs, 1-4-20, 2103, II 8402) supplied and fitted. In connection with this repairs, Lower part of Stern-frame removed, and after ^{wards} new part of Stern frame fitted together. Stern frame replaced in good order. On Starboard and E stroke plate N^o 1 removed, and replaced. C. II. and E stroke plate N^o 1 renewed -
A side: A stroke plate N^o 1 removed and replaced. C. II and E stroke plate N^o 1 renewed -
Three deep floors and 4 frames removed and replaced. Rudder trunk taken out, and refitted with one new plate. Ransom plate and six angle bars removed and replaced. Rudder unstopped. Quadrant lifted and taken off, for which the deck plate and three deck beams removed. After repairs rudder replaced in good order, quadrant refitted and connected up. Afterward steam steering gear tested under beam and found in good working condition. Deck plate and three deck beams replaced and renewed. After peak tested after repairs and found sound and tight. All broken and disturbed cement renewed, and new and repaired work painted as required -


Heavy weather damage.

Startled rivets in shell angle of tunnel recess renewed, and new angle's fitted, and four connection angle's to after peak bulkhead renewed. Startled rivets in 13 angle bars in deep tank and 8 angles on brackets in bunker renewed, and new angle's fitted.

All double ^{bottom} tanks examined internally in way of connection of floors to shell at side; and a number of shell rivets in way of connection floors to shell at sides in all double bottom tank Starboard and Port side renewed, and several rivets in shell above tank top in all holds renewed S.B. & P.S. and seams and edges recaulked. Several rivets renewed in frame brackets to tank top, and some ~~new~~ connection angle's to tank top renewed. Deep tank end internally and several startled rivets renewed in deep tank top, in bulk head between deep tank and engine room; and in tunnel in way of deep tank; and seams recaulked.

In the Engine room tank on Port side, the box for the inlet valve's riveted and angle's renewed.

Please see continuation sheet.



© 2019

Lloyd's Register
Foundation

W483-0481 3/4

S. S. KINGHORN

All double bottom tanks, and deep tank tested after repairs and found sound and tight.

All broken and disturbed cement renewed and repaired work painted or cement washed as required.

Bottom and rudder now in a good condition and recoated on fore deck under the fore castle, steam pipe covering plate refastened, and lugs on door to carpenters shop renewed.

Saloon house midships wood deck on top caulked and repayed and the panelling in the saloon to deck planks partly renewed and painted.

The hatch down to the provision room repaired, In the after side of the saloon, 3 steel doors fitted in good order, and

pipe covering plate at entrance door fastened to deck Deck houses at engine casing: The hospital cleaned out and

all wood work repaired or renewed where required, and after repairs painted The boat deck on top of the houses

caulked and repayed, Broken planks on both sides renewed and the old planks refastened where set up, Broken

wooden moulding renewed, and one holding down eye bolt for port life boat renewed, 16 new hatch batten cleats supplied

and fitted to hatch above stove hold grating. The clip of accommodation ladder renewed, Painting in stb.

foreward repaired and one length of wood renewed.

Some deck planks of bridge deck renewed - and deck recaulked and repayed where required.

Poop. Wood deck caulked and repayed, and davits overhauled three awning stanchions faired, and three wooden awning-

brackets renewed, The Stern light renewed and replaced in good order, and open rail and stanchion faired in place

Deck house on poop, Wood deck on top caulked and repayed

^{steel} wood doors for main entrance renewed, and six wood doors renewed The whole crew spaces, with cabins, messrooms, W.C.'s

washrooms etc in deck house and poop aft taken a drift and rebuilt with necessary renewals as it was before

Bent steel bulk heads faired, the Lifesil on deck renewed and properly fastened, Painting, electric light, steam heating

bunks inventory etc. are all made in good order

Electric light has been overhauled all over the ship and broken and damaged cables and wires, lamps, etc. renewed

and made good. All broken glasses of the side lights renewed and leaking side lights refastened.

Wooden flooring in tunnel repaired.

Please see continuation sheet.



© 2019

Lloyd's Register
Foundation

Rotterdam 3rd Continuation of Report No. 1273 dated 10 February on the

S.S. KINGHORN.

Collision damage - Portside
strike plate N^o 14 and 15 faired in place
the shelterdeck stinger plate removed faired and replaced
langer angle in way of same removed faired and replaced

H. P. Jonker