

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

AUG 12 1938

Date of writing Report	Aug 1 st	1938	When handed in at Local Office	Aug 1 st	1938	Port of	Kelvin, H.S.
No. in Book.	Survey held at	8 Kelvins, H.S.	Date, First Survey	July 14 th	Last Survey	July 24 th	1938 (No. of Visits 11)
7684	on the Machinery of the Wood, Iron or Steel Vessel	"Holl"					
Gross Tons	10044	Vessel built at	Pitcairn	By whom	Deutsche Kraft. A.G.	When	1930
Net Tons	5891	Engines made at	Rapstug	By whom	Deutsche Kraft. A.G.	When	1930
Normal Power	1175	Boilers, when made (Main)		By whom	Deutsche Kraft. A.G.	When	1930
of Main Boilers		Owners	Deutsche Kraft. A.G.	Owners' Address	(Donkey) 1930		
of Donkey Boilers	5	Managers		Port	Port Kelvins	Voyage	Certified
in Pressure		If Surveyed Afloat or in Dry Dock	Dry dock			Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
Main Boilers		(State name of Dock.)	Kelvin Graving Docks, H.S.				
Red D.B.	100						
Donkey Boilers	170						

1st Report No. Port

Particulars of Examination and Repairs (if any)

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and dates being entered in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

a damage report made by anyone else? If so, by whom?

The Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey "

was not done, state for what reasons?

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

latest date of internal examination of each boiler

CHARACTER. X for Special Survey Date of last Survey and of Periodical Surveys.	Years assigned expired.	Machinery and Boiler Surveys (including date of N.B., if any).
E100AI 12-37		ELMC CS6-34
S.S. Rot. No. 1-35	3-37	
Coupling Pattern in Hull.		T5 (CL) 2-37
		DRS 3-37

The donkey boilers and 1 main donkey boiler

OIL ENGINE
CONTINUOUS SURVEY

SEE LIMITATION LIST

Present condition of funnel(s) Interfacing

the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

the Surveyor examine the Safety Valves of Donkey Boiler?

Yes. 2 D.B. / 1 M.D.B.

To what pressure were they afterwards adjusted under steam? 170 and 100

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers? Yes

the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers? Yes

screw shaft now been drawn and examined?

Noticed Is it fitted with continuous liner? Yes

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Yes

shaft now been changed? If so, state reasons

the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

date of examination of Screw Shaft

July 20th

State the distance between lignum vitæ or bearing metal of stern bush and top of after bearing of screw shaft

P5/32.5/16

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? Yes

did the Surveyor examine the generators, motors, switchgear, cables and fuses?

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Survey is not complete, state what arrangements have been made for its completion and what remains to be done

C 5

Survey stated that two machined (1) through grinding at the Pilot Station, Rockside Light Vessel, River Plate, on February 23rd, 1938, on a voyage from Aruba to Buenos Aires, and through trading bottom caused twice while proceeding to Buenos Aires ends after picking up fuel, and (2) through the port machined top and hull fracturing on July 12th, 1938, while sailing to Kelvin, H.S., after picking up fuel off Aruba Island, H.S. on a voyage from Marmel to Kelvin, H.S. Further particulars see log books.

Note - Vessel had in dry dock, the propellers, stern tubes, rudder, etc. were taken out and their fastenings examined and found in good working condition. The donkey boilers were examined externally and internally with their safety valves, steam pipes, hoses and mountings and found in good working condition. The safety valves were adjusted with steam to a pressure of 170 lbs per sq. in. The bottom stem donkey boiler was examined externally and internally. Bottom stem safety valves, steam pipe hoses and mountings and found in general Observations, Opinion, and Recommendation: - The machinery of this vessel, as far as seen, is in good working condition, and eligible, in my opinion, to remain in service and to have the record of DRB 7-38 and substituted T5 38 made in the Register Book in the case of this vessel, subject to the 2 part cylinder jacket being renewed 12-38, and the repair to the 1 crank fit and top plate being repaired within six months on 1-39. As the work test indicated donkey boilers not to be used.

Fees (per Section 29)	£ : :	Fees applied for
Actual Damage or Repair Fee (if any) (per Section 29)	£ 135 :-	July 24 1938
Revolving expenses (if chargeable)	£ 30 :-	Received by me, 19

Y. Mor.

© 2020

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI 9 SEP 1938

signed As now, subject

NORWEGIAN VESSEL

DRS 7-38

If so, to be sent to
as Certificate required?

W49-0058 (1/3)

Lloyd's Register
Foundation

Star Liner Sc. "Holl"

In safe working condition. The safety valves are apparently adjusted with screw to allow at a pressure of 105 lbs. The vertical tank heat ducting tubes are not secured, it being stated these were lost to the sea when as trailers, instruction to that effect having been received by the master from the owners.

Ducting trailer repairs:- 54 pieces broken

11 spikes top bolts into trailer shell removed (part broken)

2 heat insulating tubes removed complete.

Port林耳 engine

No 1 cylinder, piston, heads, valves, top and bottom liners all opened up, top and bottom liners drawn for examination, piston and rod tried in little for truth. The crosshead was removed, tried in little for truth and found satisfactory.

The No 1, 2, 3, 4 and 5 main bearings were opened up & examined.

The crank shaft was turned in position and tested with surface gauge for truth.

The Nos 2 and 3 main bearing bolts were removed, examined, tested in little for truth, found satisfactory and all parts replaced.

The crosshead bushes and bolts were removed and existing bushes re-settled for spare.

The No 1 piston (found fractured) was removed, and piston rod replaced by spare.

The top and bottom liners (found fractured) were removed and tested.

The No 1 engine was apparently closed up in poor order.

The Nos 2 and 3 top and bushes and bolts were opened up, examined, bolts tested and all replaced and adjusted.

The broken portion of the No 1 crank pit (stated to have been broken by fractured top and bolt failing when crank was at crank pit) was repaired by fitting pointed copper patch secured by $\frac{1}{2}$ " top bolts, and tested by filling crank pit with water on completion of repairs.

The fracture on inner wall of bed plate in bay of No 1 crank pit (stated to have been sustained at the same time as the damage to crank pit) was repaired by drilling and plugging all of fracture, and the fitting of a steel patch secured by $\frac{1}{2}$ " bolts and top bolts. (For details of above see enclosed the print.)

The port main engine was tried under working conditions on completion of repairs with satisfactory results.

Starboard main engine

The No 2 cylinder, piston, heads, valves and top and bushes were opened up, top and bottom liners drawn (leaking and found fractured) and liners removed and tested.

The metal in the two lower halves of top and bushes (found cracked) was removed.

The No 2 engine was closed up after repairs completed, and starboard engine tried under working conditions on completion of repairs with satisfactory results.


The bilge pump was opened up, examined, and new bush and complete fitted, original bush and liners fully worn.

The starting slide for starboard rams were opened up, examined and adjusted.

The port and starboard escape pump pistons, cylinders and valves opened up, valves removed, cleaned, replaced and all found satisfactory.

The No 1 auxiliary engine (solen) opened up, examined, main bearing removed and the crank

J. Morris



Lloyd's Register
Foundation

W49-0058(2/3)

Rpt. 9a.

Port of

Halifax, N.S.

Continuation of Report No 2905

dated Aug 1st, 1938

on the

Old Twin Sc. "Koll"

shaft supplied by owners and fitted in alignment, cylinder and piston removed and all cleaned up in good order.

The donkey bilge pump was freed up, examined, piston rings renewed and pump placed in efficient condition.

The starboard screw shaft was turned, bearing skinned a little, stem bush re-bored, oil rings renewed, renewed, 1 bearing and sealing rings renewed, propeller blade tips joined and all replaced in alignment, also after spring bearing renewed and adjusted.

The port propeller was removed, oil ring removed for examination, 1 bearing and sealing rings renewed, and all replaced.

The port after intermediate shaft bearing was freed up and examined, and found satisfactory. Main engine cylinder and piston cooling pumps freed up, examined and adjusted.

J. Moore.