

No. 102116

Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

24 OCT 1935

23rd Oct. 1935. When handed in at Local Office 24 OCT 1935

Port of LONDON

held at LONDON

Date, First Survey

Last Survey 23rd Oct. 1935

(No. of Visits 1)

Machinery of the Wood, Iron or Steel 5/5 JAMAICA SETTLER

Vessel built at BIRKENHEAD

By whom CAMMELL LARSEN & CO. LD

When 1910-7

Engines made at DO

By whom DO

When 1910

Boilers, when made (Main) 1910

(Donkey) -

Owners JAMAICA BANANA PRODUCE CO. LD

Owners' Address -

(if not already recorded in Appendix to Register Book.)

Managers KAYE, SON & CO. LD

Port LONDON

Voyage RIVER CLYDE

If Surveyed Afloat or in Dry Dock Afloat
(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Port

Examination and Repairs (if any) INTERIM CER?

+100 AL. SHELTER ON

+L.M.C. 2-31

WITH FREEDOM 3-34

B.S. 8-35

25 L.M. N. 3-1-23

T.S. 3-34 (CL)

25 L.M. N. 2-31

+Lloyds R.M.C. 8-35

When held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of examinations and subsequent repairs. Repairs on the cause of which must be stated should be separated from repairs due to other causes; and in the body of the report, should be briefly summarised at the end of the report. State also the any letters respecting this case.

When the Surveyor has not made a special damage report he is required to state whether he is for this purpose, and why they were declined. None

When made by anyone else? If so, by whom? -

When fully go inside each Main Boiler separately and make a thorough examination at this time? No

Donkey " " " No

When for what reasons? NOT DUE FOR SURVEY

When boilers could not be thus thoroughly examined? -

When, in the absence of internal examination, were adopted by the Surveyor himself of the thorough efficiency of those parts of each boiler? -

When internal examination of each boiler? -

Present condition of funnel(s) -

When the Safety Valves of the Main Boiler? -

To what pressure were they afterwards adjusted under steam? -

When the Safety Valves of Donkey Boiler? -

To what pressure were they afterwards adjusted under steam? -

When the all the manholes, doors and their fastenings of the Main Boilers? -

, and of the Donkey Boilers? -

When the drain plugs of the Main Boilers? -

, and of the Donkey Boiler? -

When the all the mountings of the Main Boilers? -

, and of the Donkey Boiler? -

When been drawn and examined? No

Is it fitted with continuous liner? -

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

When changed? - If so, state reasons -

Has it a continuous liner? -

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

When tested been previously used? -

Has it a continuous liner? -

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

When of Screw Shaft -

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. Vessel Afloat

When when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? YES

When complete, state what arrangements have been made for its completion and what remains to be done COMPLETE.

Main engine examined generally under steam and reversing trial carried out in dock. Bilge & Ballast pumps examined under working condition and found satisfactory. Windlass and steering gear examined under steam and found to be working satisfactorily.

Vessel is now proceeding to the River Clyde where she is to be broken up.

Observations, Opinion, and Recommendation:—The machinery of this vessel as shown, what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also the action required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.&M.S. 9, 11, & L.M.C. 9, 11, or 140 lb., F.D., &c.)

When examined is in order for the contemplated voyage to the River Clyde where she is to be broken up.

INTERIM CERT
Repair Fee (if any) £ 2 : 2 : 0
If chargeable) £ - : - : -

Fees applied for 1935
24 OCT 1935
Received by Mr. J. H. 9.11. 1935

Minute FRI. 1 NOV 1935

FRI. 8 NOV 1935

H. M. Smith 2020
Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation

W490-0.234

Washburne generally
examined.
Proceeding to the Clyde
for demolition.
Jan 103 due 1st 25.

Submitted action
be referred
W/10/34