

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report \_\_\_\_\_ to \_\_\_\_\_ When handed in at Local Office \_\_\_\_\_ to \_\_\_\_\_ Port of London

No. in Reg. Book. 82426 Survey held at London Date, First Survey 10 Feb 37 Last Survey 19 February 1937 (No. of Visits 4)

on the Machinery of the Wood Transporter Steel S.S. QUARRINGTON COURT

Tonnage Gross 6900 Vessel built at Newcastle By whom Northumbland S.B. Co 1927/8 1928-11  
 Net 4330 Engines made at do. By whom Wilsend Shipry Co Ltd When 1928  
 Nominal Horse Power 569 Boilers when made (Main) 1928 (Donkey) \_\_\_\_\_  
 No. of Main Boilers 3 Owners Cant Lini Ltd. Owners' Address \_\_\_\_\_  
 No. of Donkey Boilers \_\_\_\_\_ Managers Haldin & Philippic Ltd. (if not already recorded in Appendix to Register Book.)  
 Steam Pressure in Main Boilers 180 lbs Surveyed Afloat or in Dry Dock Survey Dks. Port \_\_\_\_\_ Voyage \_\_\_\_\_  
 in Donkey Boilers \_\_\_\_\_ (State name of Dock.)

Last Report No. 107296 Port London

Particulars of Examination and Repairs (if any) B.S.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER for Special Survey Date of last Survey and of Periodical Surveys.	Machine and Boiler Surveys (including date of N.B., if any).
<u>+100 A1.</u>	<u>+LMC.</u>
<u>with grubbed.</u>	<u>M.S. 2-36.</u>
<u>6.36.</u>	<u>B.S. 1-36.</u>
<u>S.S. Nwc No 2-36.</u>	<u>T.S. (C/L) 1-36.</u>

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined \_\_\_\_\_

Was a damage report made by anyone else? If so, by whom? \_\_\_\_\_

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.

" " Donkey " " " \_\_\_\_\_

If this was not done, state for what reasons? \_\_\_\_\_

And what parts of the Boilers could not be thus thoroughly examined? \_\_\_\_\_

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? \_\_\_\_\_

State latest date of internal examination of each boiler Port 10-2-37 Centre 11-2-37 Star 15-2-37 Present condition of funnel(s) good.

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes. To what pressure were they afterwards adjusted under steam? \_\_\_\_\_

Did the Surveyor examine the Safety Valves of Donkey Boiler? \_\_\_\_\_ To what pressure were they afterwards adjusted under steam? \_\_\_\_\_

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes. and of the Donkey Boilers? \_\_\_\_\_

Did the Surveyor examine the drain plugs of the Main Boilers? \_\_\_\_\_ and of the Donkey Boiler? \_\_\_\_\_

Did the Surveyor examine all the mountings of the Main Boilers? Yes. and of the Donkey Boiler? \_\_\_\_\_

Has screw shaft now been drawn and examined? No. Is it fitted with continuous liner? \_\_\_\_\_ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? \_\_\_\_\_

Has shaft now been changed? \_\_\_\_\_ If so, state reasons \_\_\_\_\_

Has the shaft now fitted been previously used? \_\_\_\_\_ Has it a continuous liner? \_\_\_\_\_ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? \_\_\_\_\_

State date of examination of Screw Shaft \_\_\_\_\_ State the distance between lignum vite or bearing metal of stern bush and top of after bearing of screw shaft \_\_\_\_\_

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted? \_\_\_\_\_

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

How done: All three main boilers examined throughout and found in satisfactory condition. Safety valves afterwards adjusted under steam as stated above. Minor renewals and repairs to boiler mountings.

General Observations, Opinion, and Recommendation:— The machinery of this vessel  
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 2, 11, B.S. & S. 0, 11, L.M.C. 0, 11, or C.S. 3, 11.)  
as now seen is in my opinion eligible to remain as classed and to have fresh word of B.S. 2.37.

Survey Fee (per Section 29) £ 40 0 0 Fees applied for \_\_\_\_\_


Special Damage or Repair Fee (if any) (per Section 29.) £ \_\_\_\_\_

Travelling expenses (if chargeable) £ \_\_\_\_\_

Committed's Minute \_\_\_\_\_

Assigned B.S. 2.37

J.H. Milton & D.F. Chapman  
 Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

If also been held on Ship?

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

*John H. Meehan  
John H. Meehan  
John H. Meehan*



© 2020

Lloyd's Register  
Foundation