

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office OCT 12 1940)

Date of writing Report 10/10/1940 When handed in at Local Office 10/10/1940 Port of BARRY.

No. in Reg. Book 78675 Survey held at BARRY. Date, First Survey 6/9/40 Last Survey 9/10/1940 (No. of Visits 6)

on the Machinery of the ~~Wood, Iron or Steel~~ $\frac{3}{4}$ MACE DONIER

Tonnage { Gross 5227 Vessel built at GLASGOW By whom LLOYD ROYAL BELGE (G. BRUNN) Lth When 1921-4
 Net 3231 Engines made at GLASGOW By whom DUNSMUIR & JACKSON, Lth When 1921

Nominal Horse Power 567 Boilers, when made (Main) 1921 (Donkey) ✓

No. of Main Boilers 3 Owners CIE. MARITIME BELGE (LLOYD ROYAL) S.A. Owners' Address ✓
 (if not already recorded in Appendix to Register Book.)

No. of Donkey Boilers ✓ Managers AGENCE MARITIME INTERNATIONALE Port AMSTERDAM Voyage ✓

Steam Pressure in Main Boilers 200 lb If Surveyed Afloat AND in Dry Dock BARRY & GRAVINC DOCKS Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boilers ✓

Last Report No. _____ Port _____

Particulars of Examination and Repairs (if any) OKG, BS.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes

" " Donkey " " " " ✓

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler (SIBO) 6-9-40, (PORT) 11-9-40, (CRE) 10-9-40 Present condition of funnels good

Did the Surveyor examine the Safety Valves of the Main Boiler? yes To what pressure were they afterwards adjusted under steam? 200 lb/D

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes , and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? yes , and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? no Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? no

Has shaft now been changed? ✓ If so, state reasons ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? 3/32"

State date of examination of Screw Shaft ✓ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 3/32"

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted ✓

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done COMPLETE

Now DONE: Propeller and all outside fastenings examined and found in good condition.

FOR BS: the 3 main boilers with their mountings opened out and examined internally and externally. their safety valves were then adjusted under steam to the above pressure

REPAIRS: PORT BOILER: main and superheat stop valve seats, and aux. check valve seat renewed.

CENTRE BOILER: main check valve seat and lid renewed

SIBO BOILER: 5 plain tubes renewed, superheat stop valve seats renewed, and landing cracks in furnace gounlay neck seams welded. Sundry minor repairs to mountings effected.

General Observations, Opinion, and Recommendation:— the machinery of this vessel,

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, B.&H.S. 9.11, & L.M.C. 9.11, or L.M.C. 140 lb., F.D., &c.)

so far as now seen, is eligible in my opinion to remain as classed and to have fresh record of BS 10.40

Survey Fee (per Section 29) BS £ 4 0 0 Fees applied for 10/10/1940 BS

Special Damage or Repair Fee (if any) (per Section 29) £ _____ Received by me, _____

Travelling expenses (if chargeable) £ _____ 19 _____

Committee's Minute FRI 25 OCT 1940

Assigned BS 10.40

John Gustine
 Engineer Surveyor to Lloyd's Register of Shipping.

© 2021
 Lloyd's Register Foundation
 W51-0223

Pd. due 6.40 Held
minor repairs effected

It is submitted that
this vessel is eligible for
THE RECORD.

Pd 10.40

Ham.
23.10.40



© 2021

Lloyd's Register
Foundation