

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 505

of writing Report 27th August 1921 When handed in at Local Office

in Survey held at Bremerhaven

on the Machinery of the Wood, Iron or Steel Twin "VENEZUELA"

Gross 6276

Net 4210

Taxed 470

Over 5

Main Boilers 5

Donkey Boilers 5

Boilers 5

Key Boilers 5

Date, First Survey 24th March 1921 Last Survey 4th August 1921

(Received at London Office)

TUE AUG. 4 1921

10 Port of Bremen

Vessel built at Hamburg
Engines made at Hamburg
Boilers, when made (Main) 4 Boilers 1906, port forward (Donkey) boiler 1910
Owners David J. S. Co. Ltd
If Surveyed Afloat or in Dry Dock Both Hairdook

Report No. 74075A Port Newcastle-on-Tyne.

Particulars of Examination and Repairs (if any) *not any today*

All Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on being detailed in the body of the report, should be separated from Repairs due to other causes; and initials of any letters respecting this case. E 26.4.21, G.5.21, 35.1.21.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were not accepted?

Was a damage report made by anyone else? If so, by whom? ✓

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? partly, see below

" Donkey "

not done, state for what reasons? Survey held at Newcastle o. T. as per Max Report No. 74075A

parts of the Boilers could not be thus thoroughly examined?

special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor examine the Safety Valves of the Main Boiler?

Yes

Surveyor examine the Safety Valves of Donkey Boiler?

✓

To what pressure were they afterwards adjusted under steam? 200 lbs-

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

✓ , and of the Donkey Boiler?

Surveyor examine the drain plugs of the Main Boilers?

✓ , and of the Donkey Boiler?

Surveyor examine all the mountings of the Main Boilers?

✓ , and of the Donkey Boiler?

Screw shaft now been drawn and examined?

Yes

Is it fitted with continuous liner?

✓ or two liners?

or is it without liners? Yes-

Shaft now been changed? If so, state reasons

Shaft now fitted new?

Has it a continuous liner?

✓ or two liners?

or is it without liners?

Distance between stern bush and top of after bearing of screw shaft? a close fit

It is not complete state what arrangements have been made for its completion and what remains to be done? Complete

+ done:- The pumping pipes and connections & valve boxes examined and found all now in good condition and in accordance with the approved plan and the Secretary's letter. The Pulsometer pump has been replaced by a duplex pump of $8\frac{3}{4} \times 10\frac{1}{2}$ dia. by $9\frac{1}{2}$ stroke all other auxiliary pumps have been thoroughly overhauled, their sizes are: $2\frac{9}{16} \times 10\frac{1}{4} \times 17\frac{3}{4}$, $6 \times 4\frac{3}{4}$, $4\frac{3}{8} \times 5\frac{1}{8} \times 4$, $3\frac{1}{4} \times 4 \times 4\frac{3}{4}$. The main feed water heater has been tested and the evaporator safety valves adjusted under steam. Air and sounding pipes examined and found in compliance with the Rules. The 2 flywheel pumps have been overhauled & tested and the provision for draining the chain locker and the bilge and after peaks have been examined and found in order.

All boilers tested under hydraulic pressure of 270 lbs per square inch formed and without alteration of form. The furnaces of the forward starboard boiler

Observations, Opinion, and Recommendation:

clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also my alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9.11, B.&H.S. 9.11, or \pm L.M.C. 9.11, etc.

The vessel's machinery now appear to be in a sound and efficient condition and eligible in my opinion for the notification L.M.C (with date) 1st Aug. 1921. Fitted for oil fuel F.P. 150° F.

per Section 28)

or Repair Fee (if any)

per Section 28.)

Expenses (if chargeable)

£ 40 - - -

Fees applied for
per ton to Bremen
5/8/21.

Received by me,
2.9. 1921 H. C. Ramm

tee's Minute

MACHINERY CERT.
WRITING

FRI AUG. 19 1921

FRI 10 SEP. 1921

Engineer Surveyor to Lloyd's Register of Shipping

2020

L.M.C. 8.21 27
Fitted for oil fuel 8.21 & above 150° F.

R
WS10-0094

Hloyd's Register Foundation

Insert character of Ship and Machinery precisely as in the Register Book.

to the Committee.

If so, to be sent to

the Committee.

and the starboard & centre furnace of the starboard aft boiler jacked up and fished. A number of tubes removed in each boiler and upper half of main funnel removed. The boilers examined under steam found tight and their safety valves adjusted as above, thickness of washers:-

Port forward boiler	port 30 m/m	star 39.8 m/m	Superheater	18.8 m/m
Star	23 "	16.2 "	"	11.9 "
Star aft	aft 21 "	forward 21.2 "	"	14.4 "
Centre	port 28.9 "	star 17.5 "	"	25.7 "
Port	aft 23 "	forward 24.8 "	"	10.2 "

Main and auxiliary machinery tried under steam & found in order.

Repairs (Wear & Tear) Main auxiliary machinery opened out & generally overhauled, both H.P. cylinders bored out & new liners & pistons fitted, all piston & slide valve rods lined up in lathe & rebushed, a number of condenser tubes removed & condenser tested, air pump piston renewed, Starboard L.P. guide shoe remitted, all feed pump plungers rebushed, heating coils of evaporator renewed, pumping pipes partly renewed & minor repairs executed.

Alterations:- Both propellers removed and new bronze propellers with 3 not moveable blades of 14' 11" dia, 17' 9" pitch and 71.5 r.p.m per total surface fitted, at this opportunity both tail shafts drawn & examined.

The vessel has been fitted for burning and carrying oil fuel and the oil fuel burning and bilge and ballast pumping arrangements have been fitted and tested in accordance with the approved plans and the Secretary's letter E dated 6th May 1921 and in all other respects in conformity with the requirements of Section 49 of the Rules. The deep tank between frames Nos. 108 and 123 will not be used for general cargo.

A steam superheating arrangement has been fitted and tested in accordance with the approved plan and the Secretary letter E dated 26th April 1921 and a safety valve has been fitted to every portion of the superheater, which can be shut off from the boilers.

The main and auxiliary steam pipes have been re-made of steel as per plan approved 6th May 1921 and tested to 3 times the working pressure.

The approval plans of the boilers and pumping arrangements are returned. Copies of all other approved plans have been retained at London Office.