



Repairs effected.

Windlass. Driving & intermediate pinions renewed.

Aft. Star's Boiler. 2 lower inspection doors built up by riv. & refitted

Aft. Port Boiler. 2 lower manholes built up by riv. & doors refitted

Fore Star's Boiler. 2 lower inspection doors built up by riv. & refitted.  
Port safety valve lid renewed.

Fore Centre Boiler. 1 manhole (lower) and 2 inspection doors built up by riv. & doors refitted. Port & Star's safety valve lids renewed.

Fore Port Boiler. 2 lower manholes & 2 inspection doors built up by riv. & doors refitted.

Several screwed stays throughout the boilers, renewed & minor repairs carried out.

Electrical equipment examined under working conditions. Generators, cables, fittings, on main & auxiliary switch boards, distribution boxes, motor examined. Insulation resistance tested. All found or put in good order.

Repairs:- Commutators of No 1 Generator skimmed. Two brushes fitted as required, nos 2, 3, and emergency generator generally overhauled & cleaned. All motor throughout vessel examined & overhauled as found necessary. Navigation light overhauled. Fire alarm tested out & put in good working order.

Reverse current trips of main circuit breakers adjusted and tested.

W.A.

COMPLETE

N.B.—If this Report is copied by copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

W.A.  
57/24

