

R I S A L D A R

DRILL

TEST

AMIDSHIP					FORWARD					AFT				
ORIGINAL THICKNESS	By DRILLING		DIMINUTION		ORIGINAL THICKNESS	By DRILLING		DIMINUTION		ORIGINAL THICKNESS	By DRILLING		DIMINUTION	
	P	S	P	S		P	S	P	S		P	S	P	S
					.48					.48				
					.48	.56	.35	0	.13	.48	.38	.47	.10	.01
					.48	.31	.53	.17	0	.48	.47	.43	.01	.05
					.48	.29	.31	.19	.17	.48	.50	.50	0	0
.64	.55	.55	.09	.09	.48	.43	.43	.05	.05	.48	.43	.43	.05	.05
.64	.55	.55	.09	.09	.48	.30	.38	.18	.10	.48	.47	.43	.01	.05
.62	.60	.60	.02	.02	.44	.31	.38	.13	.06	.44	.41	.50	.03	0
.62	.60	.55	.02	.07	.44	.34	.31	.10	.13	.44	.38	.43	.06	.01
.62	.50	.60	.12	.02	.44	.43	.43	.01	.01	.44	.50	.48	0	0
.62	.60	.60	.02	.02	.46	.43	.47	.03	0	.46	.56	.6	0	0
.62	.75	.625	0	0	.46					.46				
.64	.65	.63	0	.01										
.68	.65	.65	.03	.03										

CEMENT

REMARKS

Bow plates marked thus*
wasted by cable chafing.
Arrangements have been
made to renew these.

Plating shaft forepe
all in good condition a
almost up to original
thickness.

W 576-0090



© 2019

Lloyd's Register
Foundation