

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

AUG - 8 1940

Date of writing Report 18 July 1940 When handed in at Local Office 19 Port of CAPE TOWN

No. in Reg. Book. 30188 Survey held at CAPE TOWN Date, First Survey 7 July Last Survey 8 July 1940  
(No. of Visits Two)

80009 on the Machinery of the Wood, Iron or Steel S.S. "NALGORA"

Tonnage { Gross 6579 Vessel built at Sunderland By whom W. Gray & Co (1918) Ltd When 1922-5  
Net 4109 Engines made at W. Hartlepool By whom Can. Mar. Eng. Works When 1922

Nominal Horse Power { 770 Boilers, when made (Main) 1922 (Donkey) ✓

No. of Main Boilers 4 Owners Brit. India Sta. Nav. Co. Ltd Owners' Address (if not already recorded in Appendix to Register Book.)  
No. of Donkey Boilers ✓ Managers Port Glasgow Voyage

Steam Pressure in Main Boilers 225 lb/sq. in If Surveyed Afloat or in Dry Dock yes (State name of Dock.)

in Donkey Boilers ✓

Last Report No. 6212 Port Bombay

Particulars of Examination and Repairs (if any) Repairs

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Has a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " " "

Was this not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler.

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Has screw shaft now been drawn and examined? Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons.

Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

Did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Complete.

It was reported that the Star. Boiler Main Stop Valve joint was leaking badly. The Stop Valve casting was removed & it was then found that the stud was broken & the flange face in way proved. The flange was faced up, stud renewed & all rejointed.

General Observations, Opinion, and Recommendation: The Machinery of this Vessel

State clearly what alterations, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0,11, B.M.S. 0,11, & L.M.C. 0,11, or L.M.C. 140 lb., F.P., &c.)

is eligible in my opinion to remain as classed

Survey Fee (per Section 20) £ 4:4:0 Fees applied for 1940  
Special Damage or Repair Fee (if any) £ 11:6 Received by me, 19  
Travelling expenses (if chargeable) £ 11:6

Committee's Minute

Assigned As now

16 AUG 1940

acting Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

WS4-0006