

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office JUL -9 1937)

Date of writing Report 18/6/37 When handed in at Local Office 18-6-37 Port of Kobe.
 No. in Reg. Book 71448 Survey held at Tama. Date, First Survey 3/6/37 Last Survey 10/6/1937.
 on the Machinery of the Steel S/S "BELFAST MARU". (No. of Visits Two.)
 Tonnage { Gross 6586 Vessel built at Kobe. By whom Kawasaki Dockyard Co. Ltd. When 1922 Smo
 Net 4038 Engines made at Kobe. By whom Kawasaki Dockyard Co. Ltd. When 1922.
 Nominal Horse Power 578 NHP Boilers, when made (Main) 1922. (Donkey) --
 No. of Main Boilers 3 SB Owners Kawasaki Kisen Kabushiki Kaisha Owners' Address (If not already recorded in Appendix to Register Book.)
 No. of Donkey Boilers -- Managers Port Kobe. Voyage --
 Steam Pressure in Main Boilers 200 lbs. If Surveyed Afloat or in Dry Dock Both
 in Donkey Boilers -- (State name of Dock.) Tama Dock.

Last Report No. Port Particulars of Examination and Repairs (if any) LMC

Periodical Surveys, when held, must be reported in detail and verification in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case. --

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined. --

Was a damage report made by anyone else? If so, by whom? --

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey " " " " --

Was this not done, state for what reasons? --

What parts of the Boilers could not be thus thoroughly examined? --

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? --

State latest date of internal examination of each boiler June, 1937

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 200 lbs.

Did the Surveyor examine the Safety Valves of Donkey Boiler? -- To what pressure were they afterwards adjusted under steam? --

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boilers? --

Did the Surveyor examine the drain plugs of the Main Boilers? -- and of the Donkey Boiler? --

Did the Surveyor examine all the mountings of the Main Boilers? Yes and of the Donkey Boiler? --

Is a screw shaft now been drawn and examined? No Is it fitted with continuous liner? -- Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? --

Is a shaft now been changed? -- If so, state reasons: --

Is the shaft now fitted been previously used? -- Has it a continuous liner? -- Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? --

State date of examination of Screw Shaft -- State the distance between top of bearing metal of stern bush and top of after bearing of screw shaft Not measured.

Engine parts, when referred to by numbers, should be counted from forward. Is electric light Yes

Is the Survey not complete, state what arrangements have been made for its completion and what remains to be done Complete.

WORK DONE:- Vessel placed in dry dock, propeller, aft end of stern bush with oil packing gland at aft end of tail shaft, sea cocks and valves with their shell fastenings examined and found in good condition.

Engine Opened up for survey:-
 All cylinders, pistons, valves, chests, rods, crank, thrust and intermediate shafting, condenser, pumps, piping and pumping arrangements examined and found or now placed in good condition.
 The 3 Main Boilers were examined over all parts with doors, mountings and safety valves and found or now placed in good condition.

REPAIRS DUE TO WEAR AND TEAR:-
 600 condenser tubes renewed on account of corrosion.
 Port boiler:- Main check valve box renewed on account of blow holes.
 2 small stays renewed.
 Other minor repairs and adjustments effected.

General Observations, Opinion, and Recommendation:- The machinery and boilers of this vessel (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, & L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)
 is in good condition and eligible, in my opinion, to be continued as classed with fresh record of LMC 6.37.

Survey Fee (per Section 29) Yen 240:00 Fees applied for 18/6/1937
 Special Damage or Repair Fee (if any) --- Received by me, 19
 Travelling expenses (if chargeable) (See Hull Report).

Committee's Minute FRI 23 JUL 1937
 Assigned + dmc 6.37
 CERTIFICATE WRITTEN

Mr. Kamakura
 Engineer Surveyor to Lloyd's Register of Shipping.
 Lloyd's Register
 W542-01010

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to