

No. 87614

Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

9 OCT 1931

When handed in at Local Office 8/10/1931 Port of NEWCASTLE-ON-TYNE
 at S. Shields. Date, First Survey 18 May Last Survey 7 Oct. 1931
 Machinery of the ~~Wood, Iron or Steel~~ Sc "AIKLEAF" (No. of Visits 5)
 Vessel built at Osaka. By whom Osaka Iron Works Ltd When 1916
 Engines made at Osaka. By whom Osaka Iron Works Ltd When 1916
 Boilers, when made (Main) 1916. (Donkey)
 Owners Dunedin Shipping Co Ltd. Owners' Address
 Managers Germann Dixon & Co Ltd. Port Newcastle. Voyage
Surveyed Afloat in the Dry Dock Middle docks.
 (State name of Dock.)

87 Port Nar

Condition and Repairs (if any) Boiler Examination

Report in detail and scirietion in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on board should be separated from Repairs due to other causes; and port, should be briefly summarised at the end of the report. State also the case.

not made a special damage report he is required to state whether he and why they were declined?

else? If so, by whom?

Boiler separately and make a thorough examination at this time? yes.

key "

thoroughly examined?

and examination, were adopted by the deficiency of those parts of each Boiler?

the Main Boiler? no

To what pressure were they afterwards adjusted under steam?

of Donkey Boiler? no

To what pressure were they afterwards adjusted under steam?

parts and their fastenings of the Main Boilers? no

, and of the Donkey Boilers?

the Main Boilers? no

, and of the Donkey Boiler?

the Main Boilers? no

, and of the Donkey Boiler?

Is it fitted with continuous liner? no

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

state reasons

Has it a continuous liner? no

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

ring metal of stern bush and top of after bearing of screw shaft

gements have been made for its completion and what remains to be done.

Finally and the following recommendations made.

up, Owners Supt states these will be carried out before

tioned.

in tubes in all boxes to renew.

Saddle + C.C back to caulk where leaking

C.C back to crop and part renew in way of 3rd, 5th row

to remove and renew

C.C back to crop and part renew in way of 3rd, 5th row of stays

tubes in each box to renew

on, and Recommendation:—

the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also

the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9/11, B.A.B.S. 9/11, or S.I.M.C. 9/11.

now seen is in my opinion eligible to remain

set to repairs to Boilers being carried out before

the machinery of

TUE 27 MAR 1934

Deferred

N.B. - If this Report is copied by any
Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Repairs

needed. To be carried
out recommended

notified

Deferrals

FRI 7 MAR 1935

Deferred

TUE. 30 APR 1935

Deferred

W.H. Mac

FRI. 13 SEP 1935

Deferred

W.H. Mac

FRI. 7 APR 1935

Deferred

W.H. Mac

FRI. 21 JAN 1936

Work now to be broken

" Gls (Copy) up

" Lxds

To R. Del. 6

Br. N.W.

FRI. 15 SEP 1935

Deferred

W.H. Mac

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020
Lloyd's Register
Foundation