

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

DEC 6 1939

Date of writing Report 19 1939 When handed in at Local Office 2 DEC 1939 Port of Liverpool

No. in Survey held at Liverpool Date, First Survey 1/12/1939 Last Survey 1/12/1939
 Reg. Book 29/65 on the Machinery of the Wood, Iron or Steel S.S. MARDINIAN (No. of Visits 1)

Tonnage Gross 2434 Vessel built at Sunderland By whom S.P. Austin & Co. Ltd When 1919 Month 8
 Net 1426 Engines made at — do — By whom Richardsons, Westgarth & Co. (Donkey) — do —

Nominal Horse Power 266 Boilers, when made (Main) 1919
 No. of Main Boilers 2 Owners Ellerman Lines Ltd Owners' Address Ellerman & Napier Ltd
 No. of Donkey Boilers 1 Managers Ellerman & Napier Ltd Port Liverpool Voyage —
 Steam Pressure in Main Boilers 180 If Surveyed Afloat or in Dry Dock Alexandra
 in Donkey Boilers ✓

Last Report No. 9799 Port Mch Completion B.S.

Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

" " Donkey " " " ✓

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓

To what pressure were they afterwards adjusted under steam? 180 lbs / 15

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓

To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? ✓ Is it fitted with continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft ✓ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft ✓

Is electric light and/or power fitted? ✓

Engine parts, when referred to by numbers, should be counted from forward.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

— See Manchester Report —

Now done:—

Boiler safety valves adjusted to pressure stated

General Observations, Opinion, and Recommendation The machinery of this vessel
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.S.M.S. 9, 11, & L.M.C. 9, 11, for ALMC 140 lb., F.D., &c.)

as far as has been seen is in good & efficient condition & eligible in my opinion to remain as now classed with Record of B.S. 11, 39 as previously recommended, subject to the tail shaft being examined at joint of liners before the end of May 1941.

Survey Fee (per Section 29) £ : : Fees applied for 19
 Special Damage or Repair Fee (if any) (per Section 29.) £ : : Received by me, 19
 Travelling expenses (if chargeable) £ : : 19

Committee's Minute

Assigned B.S. 11.39

LIVERPOOL

- 5 DEC 1939

C. Norman Stuart
 Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register
 Foundation

W 55-0146

Noted
Tues
12.12.39

SCREW SHAFT FITTED
WITH JOINTED C.L.



© 2021

Lloyd's Register
Foundation