

DESCRIPTION OF INSULATION, PROTECTION, ETC.—continued.

Are they in places always accessible YES.

What special protection has been provided for the cables in open alleyways or where exposed to weather or moisture ARMORED CABLES

IN STEEL CONDUITS FOR MAST HEAD LIGHTS, TO INDICATOR IN PLANTHOUSE, DITTO.

What special protection has been provided for the cables near galleys or oil lamps or other sources of heat ARMORED CABLE USED

What special protection has been provided for the cables near boiler casings ARMORED CABLE USED.

What special protection has been provided for the cables in engine room ARMORED CABLE USED.

How are cables carried through beams WITH LEAD BUSHINGS through bulkheads, etc. WATER TIGHT FITTINGS

How are cables carried through decks WATER TIGHT FITTINGS.

Are any cables run through coal bunkers YES. or cargo spaces YES. or spaces which may be used for carrying cargo, stores, or baggage YES.

If so, how are they protected ARMORED CABLE RUN UNDER DECK PLATES AND BEAMS FOR JUMPS

Are any lamps fitted in coal bunkers or spaces which may at times be used for cargo, coals, or baggage NO.

If so, how are the lamp fittings and cable terminals specially protected ✓

Where are the main switches and fuses for these lights fitted ✓

If in the spaces, how are they specially protected ✓

Are any switches or fuses fitted in bunkers NO.

Cargo light cables, whether portable or permanently fixed PORTABLE. How fixed PLUG BOXES.

In vessels fitted on the single wire system, how is the dynamo terminal fixed to the hull of vessel ✓

How are the returns from the lamps connected to the hull ✓

Are all the joints with the hull in accessible positions ✓

Is the installation supplied with a voltmeter YES. and with an amperemeter YES. fixed SWITCH BOARD

VESSELS BUILT FOR CARRYING PETROLEUM.

In vessels built for carrying petroleum, are all switches and fuses fitted in positions not liable to the accumulation of petroleum vapour or gas

Are any switches, fuses, or joints of cables fitted in the pump room or companion

How are the lamps specially protected in places liable to the accumulation of vapour or gas

The copper used is guaranteed to have a conductivity of not less than that of the Engineering Standards Committee's standard and the wires are protected by tinning from the sulphur compounds present in the insulating material.

Insulation of cables is guaranteed to have a resistance of not less than 600 megohms per statute mile at 60° Fahrenheit after 24 hours' immersion in water, the test being made after one minute's electrification at not less than 500 volts and while the cable is still immersed.

The foregoing statements are a correct description of the Electric Light installation fitted by us on this vessel and we declare that it is at this date in good order and safe working condition.

Canadian Comstock Co Electrical Engineers Date 15th Jan 1920

COMPASSES.

Distance between dynamo or electric motors and standard compass ABOUT 70 FEET.

Distance between dynamo or electric motors and steering compass

The nearest cables to the compasses are as follows:—

A cable carrying	Ampères	feet from standard compass	feet from steering compass
✓	25.	15.	10.
✓	✓	✓	✓
✓	✓	✓	✓

Have the compasses been adjusted with and without the electric installation at work at full power NOT YET ADJUSTED.

The maximum deviation due to electric currents, etc., was found to be _____ degrees on _____ course in the case of the steering compass.

standard compass and _____ degrees on _____ course in the case of the steering compass.

GENERAL REMARKS.

The above Electric Light Installation has been fitted on board the vessel SS. War Vixen at Halifax, N.S. and is complete, the workman-ship is material & sound and good, as far as could be seen. The above workman-ship and also the installation have been completed in a satisfactory manner and the vessel is eligible for the RECORD. ELEC. LIGHT. 2/3/20.

Committee's Minute Dec 27 New York FEB 3 1920

Report of Survey for Repairs, &c., of Engines and Boilers.

REPORT NEW YORK Jan. 22 1920
 Surveying Report 15th JANUARY 1920 When handed in at Local Office 18th JANUARY 1920 Port of HALIFAX, N.S.

Survey held at HALIFAX, N.S. Date, First Survey 18th DEC 19 Last Survey 15th JAN 1920

on the Machinery of the Wood, Iron or Steel SINGLE SCREW STEAMER "WAR VIXEN" Master JARVIS

Gross 2222 Net 2222 Vessel built at BRIDGEBURG, ONT. By whom CANADIAN FELLIS CHALMERS LTD When

Engines made at TORONTO By whom " When

Boilers, when made (Main) (Donkey)

Owners IMPERIAL MUNITIONS BOARD Port Voyage U.K.

If Surveyed Afloat or in Dry Dock 4th DRY DOCK AND WAREHOUSE (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (including date of R.R., if any).

CLASS. CONTINGENT.

Report No. Port

Particulars of Examination and Repairs (if any)

When held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of examinations and subsequent repairs. Repairs on the cause of which must be stated should be repaired from repairs due to other causes; and being detailed in the body of the report, should be briefly summarized at the end of the report. State also the initials of any letters respecting this case.

Where cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were not done?

Was a damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? PORT BOILER.

" Donkey " " " STARR UNDER STEAM.

Is not done, state for what reasons?

Parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boiler?

Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boiler?

Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boiler?

Shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes or two liners? or is it without liners?

How been changed? No If so, state reasons

How been fitted new? Has it a continuous liner? or two liners? or is it without liners?

Distance between lignum vitae of stern bush and top of after bearing of screw shaft? 4 FT.

Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete

Work at Halifax: The work was done in dry dock and a new stern tube fitted, supplied by the Builders as per Montreal 1773 invoice. All sea cocks and propeller fastenings examined and found in order.

Work at Halifax: The furnace flange connected to combustion chamber in Port Boiler, some scale with as recommended 1/2 lb. of No. 118 turbine, with the exception of the caulking at the lower part of the flange this was E.W. after consultation with the parties concerned. The water gauge was found with an external fault, raising the water height as shown on the machinery steam and found satisfactory. These engines and boilers are now in my opinion, eligible to be classed L.M.C.

Light Installation: This was completed at this port in accordance with the Rules and in a satisfactory manner. The workman-ship and also the installation have been completed in a satisfactory manner and the vessel is eligible for the RECORD. ELEC. LIGHT. 2/3/20.

Work at Halifax: The work was done in dry dock and a new stern tube fitted, supplied by the Builders as per Montreal 1773 invoice. All sea cocks and propeller fastenings examined and found in order.

Work at Halifax: The furnace flange connected to combustion chamber in Port Boiler, some scale with as recommended 1/2 lb. of No. 118 turbine, with the exception of the caulking at the lower part of the flange this was E.W. after consultation with the parties concerned. The water gauge was found with an external fault, raising the water height as shown on the machinery steam and found satisfactory. These engines and boilers are now in my opinion, eligible to be classed L.M.C.

Light Installation: This was completed at this port in accordance with the Rules and in a satisfactory manner. The workman-ship and also the installation have been completed in a satisfactory manner and the vessel is eligible for the RECORD. ELEC. LIGHT. 2/3/20.

Work at Halifax: The work was done in dry dock and a new stern tube fitted, supplied by the Builders as per Montreal 1773 invoice. All sea cocks and propeller fastenings examined and found in order.

Work at Halifax: The furnace flange connected to combustion chamber in Port Boiler, some scale with as recommended 1/2 lb. of No. 118 turbine, with the exception of the caulking at the lower part of the flange this was E.W. after consultation with the parties concerned. The water gauge was found with an external fault, raising the water height as shown on the machinery steam and found satisfactory. These engines and boilers are now in my opinion, eligible to be classed L.M.C.

Light Installation: This was completed at this port in accordance with the Rules and in a satisfactory manner. The workman-ship and also the installation have been completed in a satisfactory manner and the vessel is eligible for the RECORD. ELEC. LIGHT. 2/3/20.

Work at Halifax: The work was done in dry dock and a new stern tube fitted, supplied by the Builders as per Montreal 1773 invoice. All sea cocks and propeller fastenings examined and found in order.

Work at Halifax: The furnace flange connected to combustion chamber in Port Boiler, some scale with as recommended 1/2 lb. of No. 118 turbine, with the exception of the caulking at the lower part of the flange this was E.W. after consultation with the parties concerned. The water gauge was found with an external fault, raising the water height as shown on the machinery steam and found satisfactory. These engines and boilers are now in my opinion, eligible to be classed L.M.C.

Light Installation: This was completed at this port in accordance with the Rules and in a satisfactory manner. The workman-ship and also the installation have been completed in a satisfactory manner and the vessel is eligible for the RECORD. ELEC. LIGHT. 2/3/20.

Work at Halifax: The work was done in dry dock and a new stern tube fitted, supplied by the Builders as per Montreal 1773 invoice. All sea cocks and propeller fastenings examined and found in order.