

20 OCT 1931

No. 87646

Rpt. 8.

(Received at London Office)

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 17/10/31 When handed in at Local Office 17/10/31 Port of NEWCASTLE-ON-TYNE
 No. in Reg. Book 28594 Survey held at 16th St. St. Date, First Survey 29/10/31 Last Survey 13/10/31
 on the 16th St. St. MILLPOOL

TONNAGE Built at Stockton By whom Ropner & Sons. When 1906-10
 GROSS 4218 Owners Port Shipping Co. Ltd. Owners' Address (if not already recorded in Appendix to Register Book)
 UNDER DECK 3608 Managers Sir R. Ropner & Co. Ltd. Port belonging to W. Hartlepool
 NET 2707

Surveyed Afloat or in Dry Dock? both Name of Dock Smiths. Destined Voyage
 WB=CellDorDBa feet; uEBB feet; f feet
 total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
 If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 1766 Port APL Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? If so, by whom?
 REPAIRS, OR EXAMINATION AS PER RULE, FOR COMPLETION OF 2ND SPECIAL SURVEY No. 3.
 (see also H.P. report No. 17061).

Now done Vessel placed in dry dock, bottom & rudder cleaned & examined.
 Examined holds, lower decks, upper bunkers, engine & boiler spaces, weather decks, trunk, rudder trunk & plating in way of side lights & soil pipes.
 Oxidation removed as necessary for examination of steelwork.
 Examined masts, rigging (wedges removed), hatches, hatchways, hatch & ventilator coamings, casings, hatchways, general equipment & watertight doors. Hand pumps forward tested. Freeboard verified.
 Shell plating drilled (for results of drillings see later).

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair or Repaired								
Faired or Repaired in place								
PRESENT CONDITION OF THE								
Decks	good	State if Tanks have been examined inside	no	no	no	no	no	no
Caulking of Decks		State if Tanks now tested	no	no	no	no	no	no
Coamings		Bulkheads	good	good	good	good	good	good
Beams & Fastenings		Ceiling						
Outside Plating		Cement or Asphalt (State which)	good	good	good	good	good	good
Breasthooks		Rudder						
Transoms		Steering gear and its connections						
Frames	good	Windlass						
Reverse Frames		Have Pumps now been examined and found efficient?	yes	yes	yes	yes	yes	yes
Longitudinals		Have Sluice Valves now been examined and found efficient?	yes	yes	yes	yes	yes	yes
Transverses		Have Watertight Doors now been examined and found efficient?	yes	yes	yes	yes	yes	yes
Floors		Have Ventilators and their Coamings been examined and found efficient?	yes	yes	yes	yes	yes	yes
Keelsons	good							
Stringers								
Inner Bottom Plating								

General Observations, Opinion as to Class, Recommendation, &c.:—
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example, "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and p124, &c."

This vessel is eligible in our opinion to remain as classed & to have fresh record of survey 10/31 SRP & notation of S.S. SRP 27N°3-10/31.

Survey Fee (per Section 29) £
 Special Damage or Repair Fee (if any) £
 Travelling Expenses (if chargeable) £
 Second Surveyor's Fee (if any) £
 Fees applied for, £
 Received by me, £
 Surveyor to Lloyd's Register of Shipping.

Committee's Minute
 Character Assigned

S. S. MILLPOOL Comd

Main Boilers Examined internally & externally with mountings, doors & fastenings.

Br. Repairs: Rivets removed from the back landings of furnaces (Port Bl: Centre & starboard, St. Bl: Centre) holes re-counter sunk & rivets renewed. Landings held on water side around upper halves only. About 26 stay nuts removed & stays re-caulked. Basins and seams caulked. Mountings overhauled.

Machinery Repairs: Main Steam Pipe annealed & tested as per Rules.

Cranks lifted, all main bearing lower halves remounted & shaft re-buffed. All recent shafts remounted & re-adjusted. M.P. Slide valve & loose face machined. L.P. Piston packing ring refitted. Junk bin machined. Air pump refitted to Condenser. Main Condenser fitted out, tubes cleaned & all ferrules renewed, afterwards tested. Feed Pump rooms skinned up, gland such bushes renewed. H.P. Crosshead bearing (top half) renewed. Pump crosshead bearings built up by electric welded & machined, brasses re-adjusted. General Service Pump suction & delivery valves renewed seats machined.

N.B.—If this Report is copied by copying press, special care must be taken that the copying paper is not so much damp as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register Foundation