

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report Feb 5th 1937 When handed in at Local Office Feb 5th 1937 Port of LONDON

No. in Reg. Book. Survey held at TILBURY. Date, First Survey 9 Last Survey Feb 4th 1937

72039 on the ~~Wood, Iron or Steel~~ S.S. BRITISH ENSIGN

TONNAGE:- Built at Newcastle. By whom Armstrong Whitworth & Co. Ltd. When 1917 MONTH. 9.
GROSS 1048 Owners British Tankers, B. & S. Ltd. Owners' Address (if not already recorded in Appendix to Register Book).
UNDER DEK. 6463 Managers See letter Port belonging to London.
NET 4390

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Gravesend. Destined Voyage Hull or Rotterdam.
WB=Cell D B or D Ba feet; A E & B feet; f feet
total capacity tons. FBT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 8954 Port Fal

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Yes. No.

CHARACTER.	Years Assigned	Machinery and Boiler surveys
* For Special Survey. Date of last Survey and of Periodical Surveys.	extended.	(including date of N.B., if any).
* 100 A1 T.36. SS. SHL N° 3. 8.29. SS. FAL N° 1 33. Carrying Petroleum in Bulk.		* LMC MS. 10.33. BS. 4.36. TS. ⁽⁶²⁾ 11.7.34 8.17.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

required. Was a damage report made by anyone else? If so, by whom? No.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Heavy weather damage.

It is stated that this vessel sustained damage to the steering gear through encountering heavy weather off Finisterre on January 27th 1937.

Found:- Quadrant port anchor pin carried away and hand steering gear guides and crosshead bent.
Now done:- Two new anchor pins fitted, spare buffer fitted, Port & Starboard deck stops refitted.
As temporary repair in lieu of hand steering gear:- Wire rope blocks and tackle fitted to quadrant and after winch. Steering gear tried under P.T.O.

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year.
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained. (State if wedges removed).
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
" " in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged)
Reverse Frames	Have Stairs Valves now been examined and found efficient?	Caulking ditto	" length mean diamr. (on board)
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" Rule length size
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Hawser & Warps
Floors		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Keelsons		Timbers of Frame at openings ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Shells ditto	
		Salting ditto	
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:— This vessel is State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,2,4," or "to remain as classed and to have record of survey, 1,2,4, and the notations of ss No. 1-24 and ptND24, &c."

in good condition and eligible in my opinion to remain as classed without fresh record of survey subject to the hand steering gear being repaired at the first convenient opportunity.

Survey Fee (per Section 29) £

Special Damage or Repair Fee (if any) (per Sec. 29) £ 3 3 0

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for, 6 FEB 1937

Received by me, 23/2/37

Arthur W. Oxford
Surveyor to Lloyd's Register of Shipping.

Committee's Minute

FRI 19 FEB 1937

FRI 19 MAR 1937

Character Assigned

As now subject
Click Out, be.
W. H. Dwyer
for R. Dept



Lloyd's Register
Foundation

W568-0059

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Uf Stocklen, *State Mechanical Tests*

If Stockless, state Mechanical Tests

If Stockless, state Mechanical Tests

2

2

2