

Report of Survey for Repairs, &c., of Engines and Boilers.

20 SEP 1930

(Received at London Office)

18 SEP. 1930

Port of LIVERPOOL

of writing Report

19

When handed in at Local Office

in Survey held at Liverpool

Date, First Survey 1st Sept

Last Survey 16th Sept 1930

(No. of Visits 5)

460 on the Machinery of the Wood, Iron or Steel Twin S.C. S. "ORITA"

Gross 9298
Net 5811

Vessel built at Belfast

By whom Harland & Wolff, Ltd.

When 1903-8.

Engines made at Belfast

By whom Harland & Wolff, Ltd.

When 1903

Boilers, when made (Main) 1903

(Donkey)

Owners Pacific Ste. Nav. Co.

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port Liverpool

Voyage

of Main Boilers 30

of Donkey Boilers 1

Pressure Main Boilers 210 lb.

Donkey Boilers 1

Managers

Surveyed Afloat in Dry Dock Canada 50x

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER
* for Special Survey.
Date of last Survey and of Periodical Surveys.

Years assigned for survey.

Machinery and Boiler Surveys (including date of N.B., if any)

100 A1
9.28

LMC 6.24
BS 6.29
TS(24) 3.30.

U.Liv. N°3-10,16
U.Liv. N°2-25.

Fitted for oil fuel 720 F.P. above 150° F.

st Report No.

Port

Particulars of Examination and Repairs (if any) Ship, Comp. LMC & BS.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.

Do. " Donkey " " "

Was this not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes

To what pressure were they afterwards adjusted under steam? 210 lb.

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes.

, and of the Donkey Boilers? Yes

Did the Surveyor examine the drain plugs of the Main Boilers? Yes.

, and of the Donkey Boiler? Yes

Did the Surveyor examine all the mountings of the Main Boilers? Yes.

, and of the Donkey Boiler? Yes

Was screw shaft now been drawn and examined? No

Is it fitted with continuous liner? Yes

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Yes

Was shaft now been changed? If so, state reasons

Was the shaft now fitted been previously used? Yes

Has it a continuous liner? Yes

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Yes

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft Good fit.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Completion of LMC 6.29. (See Liv. Rpt. 96763)

Vessel placed in dry dock, propellers, sea connections and their fastenings examined and now in good order. Stern bushes a good fit.

Examined Starboard Engine cylinders, pistons, slide valves & casings, crank, thrust & tunnel shafts, air, circulating, feed & bilge pumps, condenser under test and pumping arrangement and now in good order.

Electric installation examined generally & tested under working conditions, fuses in order, cables examined as far as practicable and found satisfactory.

Boiler Survey: Main boilers examined internally & externally with their safety valves, doors and mountings and now in good order.

Boilers and steam pipes examined under steam and safety valves adjusted as above.

General Observations, Opinion, and Recommendation: The machinery of this vessel as seen

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, B.&M.S. 9.11, or L.M.C. 9.11, 140 lb., F.D., &c.)

is eligible in my opinion to remain as classified with full record of LMC 6.29 as previously recommended and BS 9.30.

Survey Fee (per Section 28) BS £ 10: - : -

Special Damage or Repair Fee (if any) £ : : :

Travelling expenses (if chargeable) £ : : :

Committee's Minute

Assigned

LIVERPOOL

+ L.M.C. 6.29.

B.S. 9.30.

Fees applied for

19 SEP. 1930

Received by me,

9.10.1930

TUE. 3 NOV 1930

19 SEP. 1930

23.2.31

Engineer Surveyor to Lloyd's Register of Shipping.

W581-0054

Lloyd's Register Foundation

Is a Certificate required? If so, to be sent to

St. No 3 due 10.28 Completed

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

St. due 6.30 held

It is submitted that
this vessel is eligible for
THE RECORD.

St. 6.28

St. 9.30

St. 10.30

St. 10.30

St. 10.30

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation