

Engine Room ...
TONNAGE FOR FEES...
Loss Engine Room

4705.92
1541.02

Proportions Depth to Length
Upper Deck Beam at
side to top of keel

Residence London

50,8,12.

10 APR 1934 F.E.

Received by Chief Ship Surveyor 6/12/32.

Received from Chief Ship Surveyor

VESSEL'S NAME *At SS Cheniston* Rpt. *Old* No. *25519*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Transverse No. *80.75* Depth "d" *18' 3"*
Framing: Table No. *3 Page 15* Description *Bulk angle as*
Longitudinal No. *31492* *Approved.*

Proportions Length = *10.12*
Depth =

Bridge Deck Sheerstrake as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ 100A-1. (Stat.) as recommended.*

+ 100A-1. (Stat.)

222 (Stat)

WB. Hull D Ba 135 u 6 22 f 168 10366 FPT 1206 APT 1886
FK. 60H Cum. Lloyd's at 60 P33 3115 F36

WS89-0187



© 2020

Lloyd's Register
Foundation

Angles on upper edge
Spacing

Tie Plates
Deck, Material and thickness
Bridge Deck Stringer Plate, br'dth & thickness