

Do. of Forecastle 32.49
Do. of Houses on Deck 181.58
Do. of ^{CHIFF HOUSE} Hatchways 6.07

Transverse Number
Length on deck from fore part of stem to after part of

When built 1910

(3,000,4,0.)

Received by Chief Ship Surveyor 14/2/10.

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl. S. S. "Lacique"* Rpt. *Sld.* No. *24344*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry

It is submitted that, before this case receives the consideration of the Committee, the Sunderland Surveyors should be requested to state whether they are in error in giving the diameter of the main piece of the rudder at heel as $7\frac{1}{2}$ " in view of the diameter required by the Rules being 8."

Lx. Sld.

15/2/10.

EM

N.H.
15/2/10



© 2020

Lloyd's Register
W598-0217
Foundation

BEAMS, Forecastle Deck, Angle, Bulb Angle,
Plate, Tee Bulb or Channel
Angles on upper edge
Spacing

" Tie Plates
" Deck. Material and thickness
Forecastle Deck Stringer Plate, b'dth & th'kns
" Angle on ditto