

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

When handed in at Local Office

5 AUG 1932

Port of Sunderland

Reg. Book.

Date, First Survey

May 2

Last Survey

31

July 29 1932

No. in Survey held at Sunderland

5.5."LA. CRESCENTA

65988 on the Wood, Iron or Steel

TONNAGE

GROSS 5890

UNDER D.W.T. 5631

NET 3531

Built at Middlesbrough Hill-on-Tees. By whom Furness S. B. Co. Ltd.

Owners Crescent Navigation Co. Ltd.

Managers Harris & Dixon, Ltd.

Owners' Address

(If not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Both Name of Dock Greenwells Dock & Quaystined Voyage

WB=Cell DBor DBa feet; uE&B feet; f feet | feet | feet | tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4289 Port

Bdx

CHARACTER,
for Special Survey,
Date last Survey and of
Periodical Surveys.Years
since
last
survey
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).

+ 100 A.I. 1.32.

+ L.H.C. 9.30

5.5. Bry. W2-30

B.S. 2.32

Carrying petroleum
in bulk.C.L. 9.30
7.23

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined Yes. Mr Rogers.

Not required

Was a damage report made by anyone else? If so, by whom? Yes Mr Spark.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage stated to have been caused through
 stranding in the River Gironde off. Bec d'Ambie on the 20th & 21st April
 1932. whilst on a voyage from Port Arthur to Bordeaux
 Vessel placed in dry dock, bottom andudder
 cleaned, examined, placed in good condition and recoated.
 All main cargo tanks, summer tanks, double bottom
 and peak tanks, also condensers examined internally and tanks
 tested to rule requirements. On completion of repairs tanks retested to
 rule requirements.

Damage repairs effected.

P.T.O

SUMMARY OF DAMAGE REPAIRS:	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:
Renewed	500	-	-	-	-	2	2	Patched
Removed and Fair'd or Repaired	-	-	-	-	-	-	-	No body repair.
Patched or Repaired in place	1	-	-	-	-	-	-	

PRESENT CONDITION OF THE

Decks	Good	State if Tanks have been examined inside	Yes	Ding. Plates under Sounding Pipes	Good	Copper, or Y.M. of Wood Vessels
Caulking of Decks	--	State if Tanks now tested	Yes	Engine Room Skylights	Good	(State if on Feet). When put on, Month Year
Coamings	--	Bulkheads	Good	Coal Bunkers, Open'gs, Lids, &c.	-	Boats
Beams & Fastenings	--	Ceiling	-	Scuppers	-	Masts, Yards, &c.
Outside Plating	--	Cement or Asphalt (State which)	-	Cargo Hatchways	Good	Condition, how ascertained
Breasthooks	--	Rudder	Good	Hatches (ditto)	-	(State if wedges removed)
Transoms	--	Steering gear and its connections	-	Planking of Wood Vessels	-	Sails
Frames	--	Windlass	-	Caulking ditto	-	Equipment letter
Reverse Frames	-	Have Pumps now been examined and found efficient?	No	Treenails ditto	-	Anchors, No. of
Longitudinals	Good	Have Shut-off Valves now been examined and found efficient?	No	Breasthooks & Stemson ditto	-	3 B. 15
Transverses	--	Have Watertight Doors now been examined and found efficient?	No	Transoms, Pointers, & Crutches ditto	-	Cables (State if now ranged)
Floors	-	Have Ventilators and their Coamings been examined and found efficient?	Yes	Timbers of Frame at openings ditto	-	No
Keelsons	-			Ditto ditto at other places ditto	-	Length on board
Stringers	-			Stringers, Clamps & Shelves ditto	-	Rule length complete
Inner Bottom Plating	Good			Salting ditto	-	Hawsers & Warps
				(State if examined)	-	Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss. No. 1-24 and pTND21, &c."

This Vessel is eligible, in my opinion, to remain as classed with Fresh Record 7.32.

Survey Fee (per Section 29)

£ : : Fees applied for,

Special Damage or Repair Fee (if any)
(per Sec. 29)

£ : : 19

Travelling Expenses (if chargeable)


£ : : Received by me,

Second Surveyor's Fee (if any)

£ : : 19

Committee's Minute

Character Assigned



W. Caldwell 2019

Surveyor to Lloyd's Register of Shipping

Lloyd's Register
Foundation

6 AUG 1932

on the

Shell plates w^o from forward
but stroke no 1 plate renewed

Starboard side A stroke no 1 plate faired in place. w^o 7 plate renewed.

"L" (star) stroke w^o 8 plate renewed

"F" stroke no 1 plate cropped and paint renewed.

Bow side "A" stroke w^o 6 plate renewed.

"L" star stroke w^o 8 plate renewed.

Bilge keel no 1 length starboard side faired in place

no 3 and 4 lengths port side removed, faired and refitted.

Deck plates Starboard side w^o 6 deck strungers renewed

w^o 7 C stroke deck plate renewed. 2 lengths of gunwale
angle in way of strungers renewed faired and refitted
with new back bars.

Port side of decks as for foregoing starboard side.

Engine Room Tank Top.

Port and Starboard heavy tank top plates renewed
frame foot brackets with connections renewed for
access and refitted

A large number of shell bulkhead and Boiler room
tank top and tank end plates renewed.

Examined decks, hatches, hatchways, ventilations & coamings,
windlass, steering gear, deck openings and general
equipment. Fuel board re-assigned.

W. Caldwell.



© 2019

Lloyd's Register
Foundation

W604-0037 2/2