

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

31 MAY 1933)

Date of writing Report 29th May 1933. When handed in at Local Office 29 MAY 1933 Port of LIVERPOOL

No. in Reg. Book. 56457 Survey held at Liverpool. Date, First Survey 1st May Last Survey 29th May 1933. (No. of Visits 2)

56457 on the Machinery of the Wood Iron or Steel Lim. Co. "Aronoi"

Gross Tonnage 3365. Vessel built at Belfast By whom Harland & Wolff Ltd When 1908.

Net Tonnage 3914. Engines made at Belfast By whom Harland & Wolff Ltd When 1908.

Nominal Horse Power 816. Boilers, when made (Main) 1908. (Donkey)

No. of Main Boilers 4. Owners African S.S. Co. Owners' Address Liverpool Voyage

No. of Donkey Boilers 1. Managers African S.S. Co. (if not already recorded in Appendix to Register Book.)

Steam Pressure in Main Boilers 215 lb. If Surveyed Afloat or in Dry Dock Afloat. Port Liverpool.

in Donkey Boilers ✓. (State name of Dock.) Harwood Dock

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Last Report No. 99047 Port Liv

Particulars of Examination and Repairs (if any) part - DS.

Special Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the date and initials of any letters respecting this case.

Where cases where the Surveyor has not made a special damage report he is required to state whether he has declined his services for this purpose, and why they were declined.

Has a special damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ford only

Did the Surveyor personally go inside each Donkey Boiler?

Where any part of the examination was not done, state for what reasons?

Were any parts of the Boilers could not be thus thoroughly examined?

Were any special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? ford only To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ford only , and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? ford only , and of the Donkey Boiler?

Has a new shaft now been drawn and examined? No Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has an old shaft now been changed? If so, state reasons

Has a new shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

What is the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

To Complete the DS the remaining 3 boilers to be examined and safety valves of all boilers adjusted under steam. The vessel is now laid up & this will be done later.

Examined the ford boiler externally and internally together with its mounting and found same in good condition.

Examined the ford boiler externally and internally together with its mounting and found same in good condition.

Examined the ford boiler externally and internally together with its mounting and found same in good condition.

General Observations, Opinion, and Recommendation:—

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,11, B.M.S. 9,11, or L.M.C. 9,11, 140 lb., E.D., &c.)

The machinery of this vessel is in safe working condition and eligible in my opinion to remain as classed with fresh record of DS 5.33 on completion.

Survey Fee (per Section 20) (Arch 10/6/33) £ 1

Special Damage or Repair Fee (if any) (per Section 20.) £ :

Travelling expenses (if chargeable) £ :

Committee's Minute LIVERPOOL

Assigned Deferred for comp

Fees applied for

19

Received by me, 21.6 1933

FRI. 29 DEC 1933

R. Bauman 2020
Engineer Surveyor to Lloyd's Register of Shipping.

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to

