

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

10 NOV 1928

Date of writing Report 5th November 1928 When handed in at Local Office 6th November 1928 Port of Gotthenburg

No. in Book. Survey held at Gotthenburg

Date, First Survey 20th September Last Survey 27th October 1928
(No. of Visits) 9

4891 on the Machinery of the Wood, Iron or Steel Vessel "AUSTRALIC"

Gross 4010 Date, First Survey 20th September Last Survey 27th October 1928
Net 2530
Nominal Horse Power 435
No. of Main Boilers 2
No. of Donkey Boilers 1
Steam Pressure—
in Main Boilers 180 lbs
in Donkey Boilers 180 lbs

Vessel built at Newcastle By whom Hawthorn, Leslie & Co. Ltd. When 1907-9

Engines made at Newcastle By whom Willard Gray Co. Ltd. When 1907

Boilers, when made (Main) 1907 (Donkey) 1907

Owners Rederiaktiebolag Transatlantic Owners' Address
(if not already recorded in Appendix to Register Book).

Manager G. Carlsson Port Gotthenburg Voyage

If Surveyed Afloat or in Dry Dock Both.

(State name of Dock) Lindholmen.

Last Report No. Port

Particulars of Examination and Repairs (if any) Damage Part B.S. & I.L.S.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he

offered his services for this purpose, and why they were declined Offered to owners. Not required

Was a damage report made by anyone else? If so, by whom? None made.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " "

This was not done, state for what reasons! Donkey boiler not made ready for survey.

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes

Did the Surveyor examine the Safety Valves of Donkey Boiler? No

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

Has shaft now been changed? No If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? 3" max

The Survey is not complete, state what arrangements have been made for its completion and what remains to be done? See below.

Damage stated to have been caused by heavy weather in June 1928 while on a voyage from Delagoa Bay to Durban.

The propeller, propeller shaft, stern tube and fastenings of the sea connections examined.

The main boilers examined internally with safety valves and mountings and their safety valves adjusted under steam as above.

Repairs effected due to damage.

The after liner of the stern tube found cracked at after end and was drawn and welded electrically.

P.T.O.

General Observations, Opinion, and Recommendation: The machinery of this vessel is eligible

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9/II, B&M.S. 9/II, or B.L.M.C. 9/II, 140 lbs. F.D., &c.)

In my opinion to remain as now classed in the Register Book and to have notation of tail shaft seen 10.28 and when the survey is completed to have record of 35 10.28 subject to starboard furnace of port boiler and port furnace of starboard boiler be specially examined or renewed at next boiler survey.

Survey Fee (per Section 28).....

Rs. 90.00

Fee applied for

6th Nov 1928

Total Damage or Repair Fee (if any).....

Rs. 110.00

(per Section 28)

Rs. 60.00

Duties

Rs. 7.00

Velling Expenses (if chargeable).....

Rs. 25.00

Total fee

Rs. 25.00


Received by me,

4 12 1928

G. C. Alb

Committee's Minute

TUE. 27 NOV 1928

as now
subjectE. Barnetts 2020
Engineer Surveyor to Lloyd's Register of Shipping.Lloyd's Register
Foundation
W621-0746 1/2

Rpt. 9a.

Port of Gothenburg

Continuation of Report No. 7319 dated 6 November 1928 on the

Steamer "AUSTRALIC" No. 64891 in the Register Book.

The after end of the stern tube found smashed at bottom and to obtain a good rest for the liner the murrice was built up by electric welding.
Lignum vitae in stern tube partly renewed.

Repairs effected due to wear and tear.

Port boiler:

1 main check valve renewed.

1 donkey " "

1 lengthgoing crack in starboard furnace welded electrically.

3 leaky rivets in starboard combustion chamber made good by electric welding.

Starboard boiler:

1 main check valve renewed.

the whistle valve with seat & valve chest renewed.

3 lengthgoing cracks in port furnace welded electrically.

3 leaky rivets in centre combustion chamber made good by electric welding.

1 screw stay in centre combustion chamber renewed.

S.R. list.

Starboard furnace of port boiler specially examined, and the repairs carried out as per Goth. report No. 7133 found good. As this furnace as well as port furnace of starboard boiler at several occasions have been repaired by electric welding and still show tendency to crack it is recommended that these furnaces be specially examined or renewed at next boiler survey. The cracks appear to arise when the fire in the boilers is extinguished. Two new furnaces have been placed on board now to be fitted at a suitable opportunity.

Please see test sheet attached.

To complete boiler survey.

The donkey boiler to be examined internally with safety valves and mountings and its safety valves to be adjusted under steam.

The Owners states that this will be done at first suitable opportunity.

Alterations in connecting with fitting of deep tanks for carrying vegetable oil as cargo.

Continued.

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

5m.2.27.

Heating coils fitted and bilge piping altered in accordance with plan No. 13013 approved on the 29th September 1928.

Heating coils tested by water pressure to 26 kgs/cm² and bilge pipes in way of the deep tanks tested by water pressure to 5 kgs/cm².

The cargo oil will be pumped out by means of shore pumps.

Part of this survey was carried out by the undersigned E. Berndtsson on Thursday the 25th October from 6.30 to 10. a.m. and on Saturday the 27th October from 6.30 to 11 a.m.

E. Berndtsson.

RETIRED

Heavy weather damage Screw shafts
examined & repairs effected

B.S. due 10.28 Non not held to complete at first opportunity.

Star furnace of port boiler specially examined. Piping in Dead tank fitted for

It is submitted that this vegetable oil
vessel will be eligible for

the record B.S. 10.28 when the D.M.S. has been held throughout

It is submitted that

This vessel is eligible to remain as OLD S.S.D. July

To star furnace of port
M.B. & port furnace
of star boiler being
specially exam.
at next B.S.

(2)

36/1/28.

S10.28

