

Jt. 9.

No. 4422

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

21 JUL 1930

24 June 30.	When handed over Local Office	24/6/30 Port of SINGAPORE
Survey held at SINGAPORE	Date, First Survey 17 June 30. Last Survey 20 June 1930.	(No. of Visits 3.)
on the Machinery of the Wood, Iron or Steel G. S. "PERLAK"		
Gross 1899	Vessel built at Rotterdam	By whom Maats Tyndall When 1904-11
Net 1103	Engines made at "	By whom " When "
Final Power 215	Boilers, when made (Main) 1904	(Donkey) 1924 1921
Main Boilers 2	Owners Anglo-Saxon Petroleum Co. Ltd.	Port air dry Voyage
Donkey Boilers 1 Pressure 180 lbs	Managers	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
Donkey Boilers 180 -	If Surveyed Afloat or in Dry Dock Port. Kepulauan Harbour.	

1st Report No. Port

## Particulars of Examination and Repairs (if any) BS. TS. Dorking.

Indicate Survey, when held, must be reported in detail and variation in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and these being detailed in the body of the report, should be briefly summarised at the end of the report. State also the letter and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Is a damage report made by anyone else? If so, by whom?

Does the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. Donkey " "

Was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Has a screw shaft now been drawn and examined?

Has a shaft now been changed?

Has the shaft now fitted been previously used?

Is it a continuous liner?

Is it an approved appliance fitted at the after end of the shaft to permit of its being efficiently lubricated?

Are the distances between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft Bushes Reversed working fit.

Is the Survey not complete, state what arrangements have been made for its completing and what repairs to be done?

How done. Propeller, sea connections, sea cocks and valves (opened out) and tail end

shaft examined and found or put in good order.

The two main and the donkey boilers opened up and together with their mountings

examined and found or put in safe working order. Safety valves adjusted under

steam to above pressures.

Repairs. Stern bush completely rewooded. Tail shaft after liner dressed off. A few

minor boiler and engine repairs carried out.

Completely.

The machinery of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also

any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 6.11, B.R.M.S. 6.12, or S.P.E.R.C. 6.11,

200 lb. F.B., &c.)

As far as now seen is in my opinion eligible to remain as now classed

and to have records of B.S. 6.30 and Tail shaft un (2 liners) 6.30.

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also

any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 6.11, B.R.M.S. 6.12, or S.P.E.R.C. 6.11,

200 lb. F.B., &c.)

Assigned

Committee's Minute

Assigned

Survey Fee (per Section 28) \$120/-

Special Damage or Repair Fee (if any) per Section 28) \$40/-

Travelling expenses (if chargeable) \$15/-

Committee's Minute

Assigned

B.S. 6.30

&lt;p

B.S. due 11.30 Held

Docking. T.s drawn

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that  
this vessel is eligible for  
THE RECORD

B.S. 6.30.

(a)  
29/7/20

S. 6.30

SCREW SHAFT  
WITH JOINTED

\* THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

