

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office WED 4 MAR. 1922)

Date of writing Report March 2<sup>nd</sup> 1922 When handed in at Local Office March 2<sup>nd</sup> 1922 Port of NEWCASTLE-ON-TYNE

No. in Reg. Book 33464 Survey held at North & South Shields Date, First Survey 15 Feb. Last Survey Mar 17<sup>th</sup> 1922  
(No. of Visits 7)

on the Machinery of the Wood, Iron & Steel S/S "TREDENHAM."

Tonnage: Gross 8435 Net 5369 Vessel built at Bremen By whom Akt. Ges. Weser When 1915

Registered Horse Power 542 Engines made at Bremen By whom A. G. Weser When 1915

No. of Main Boilers 4 Boilers, when made (Main) 1915 (Donkey)   
No. of Donkey Boilers 1 Owners Hain S.S. Co. Ltd (B. Hain Hon. Mgrs) Port St. Ives Voyage Galveston U.S.A.

Steam Pressure in Main Boilers 213 lb. Surveyed Afloat  in Dry Dock Middle Dock, Black Jetty, Liverpool Whitehall Point Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. \_\_\_\_\_ Port DOCKING + B.S.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?  Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.

Do. " Donkey " " " None.

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of these parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes. To what pressure were they afterwards adjusted under steam? 213 lb.

Did the Surveyor examine the Safety Valves of Donkey Boiler?  To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes. , and of the Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? Yes. , and of the Donkey Boiler?

Has screw shaft now been drawn and examined? No. Is it fitted with continuous liner?  Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? No. If so, state reasons

Is the shaft now fitted new? No. Has it a continuous liner?  Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? 1/8" Complete.

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

Vessel placed in dry dock.  
Propeller and fastenings of stern bush and of sea connections examined and put in order. Propeller blades badly pitted. 4 new bronze propeller blades now fitted.

B.S. The main boilers and their mountings & safety valves examined and found in order.

The safety valves adjusted under steam as above.

General Observations, Opinion, and Recommendation: This vessel's machinery so far as seen is in order and eligible in my opinion to have the record of B.S. 3-22 in the Register Book.

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon the survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 2-11, B.S. 3-11, or G.L.M.C. 2-11, 140 lb., E.D., &c.)

Survey Fee (per Section 25) £ 5.00 Fees applied for 7/3/22

Special Damage or Repair Fee (if any) £ \_\_\_\_\_ Received by me, 24.3.1922

Travelling Expenses (if chargeable) £ \_\_\_\_\_

Committee's Minute TUE. 21 MAR. 1922

Assigned L.N.B. 1.21 B.S. 3.22 J.D.W.F.D. 4 APR. 1923 TUES. 19 AUG 1924

FRI. 7 AUG 1925  
TUES. 16 MAR 1925  
J. Robertson  
Engineer Surveyor to Lloyd's Register of Shipping.  
FRI. 20 JUN 1923  
TUE. SEP. 25 1923  
FRI. 1 FEB. 1924  
TUES. 25 AUG 1925  
FRI. 19 DEC 1924  
TUES. 5 JAN 1926

Insert character of ship and machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to \_\_\_\_\_

W630-035

P.S. due 1. 22 now held

It is submitted that  
this vessel is eligible for  
THE RECORD. BS3.22.

X.B. - If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Subject to the hull being  
classified.

JW  
13/3/22

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

© 2021



Lloyd's Register  
No. in Survey  
Reg. Book  
577  
Master

Rpt. 4.

Engine made at  
Registered Horse Power

ENGINES,  
No. of Cylinders

between the beam  
lines are fitted  
Dia. of Tunnel's  
columns 16 5/16

No. of Reed  
No. of Bilge  
No. of Donkey  
In the Room

of Bilge  
Are it connect  
Are they fixed  
they each fit  
pipes are

Are the  
the Bilge

of the  
Screw

BOILERS,  
Total Heating  
Working Pressure

Plus each boiler  
boiler

Smallest distance  
Thickness 1 1/4  
Along, section D

Per centages of  
Size of component  
Length of plate

Working pressure  
Material of  
Material of  
Area of  
Thickness 1 3/4

Per centages of  
Thickness of  
Working pressure

Material of  
Material of  
Area of  
Thickness 1 3/4

Per centages of  
Thickness of  
Working pressure

Material of  
Material of  
Area of  
Thickness 1 3/4