

Report of Survey for Repairs, &c., of Engines and Boilers.

THU. 10 MAY 1917

(Received at London Office)

Date of writing Report 5th May 1917 When handed in at Local Office 5th May 1917 Port of Newcastle on Tyne
 No. in Book 41 Survey held at Woburn & Shields Date, First Survey 27 Mar Last Survey 5th May 1917
 on the Machinery of the Wood, Iron or Steel S.S. Tipton Master H.S. Lake
 Gross 3569 Vessel built at Shields By whom Redhead & Sons When 1904
 Net 2300 Engines made at do By whom Redhead & Sons When 1904
 Registered Horse Power 305 Boilers, when made (Main) 1904 (Donkey) 1917
 No. of Main Boilers 2 Owners Horton & Co Port London Voyage
 No. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock Both
 Main Pressure 180 (State name of Dock) Woburn Dock
 No. of Donkey Boilers 100 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, &c. for Special Survey, Date of last Survey and of Periodical Surveys.	Year Assigned and Annual Survey.	Machinery and Boiler Surveys (including date of N.B., if any).
100 PL	9-15-15	L.M.C.
RR 2-13		BS 9-15
		FS 10-15

Particulars of Examination and Repairs (if any) L.M.C.
 Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.
 Do. " " Donkey " " Yes. (now put on shore)

Where this was not done, state for what reasons?
 What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
 Did the Surveyor examine the Safety Valves of the Main Boiler? Yes

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes (new)
 Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes

Did the Surveyor examine the drain plugs of the Main Boilers? Yes
 Did the Surveyor examine all the mountings of the Main Boilers? Yes

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? or two liners? or is it without liners?
 Has shaft now been changed? No If so, state reasons

Has the shaft now fitted new? Yes Has it a continuous liner? or two liners? or is it without liners?
 State the distance between lignum vite of stern bush and top of after bearing of screw shaft? 3/16 full

Where the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

Cap the propeller, aft end of stern bush & sea cock fastenings, the cylinders, pistons, slide valves, crank, thrust & tunnel shafts, air, circulating, bilge & feed pumps, condenser, steam steering gear & windlass. Repairs carried out, New air & circulating pump rods fitted, feed & bilge pump plungers skinned up, gland bushed & neck rings fitted, New pump link crosses and new turning gear bracket fitted, Main steam pipes annealed & tested & repaired.

On the main boiler their safety valves & mountings. Repairs carried out six new Dighton furnaces fitted, all plain tubes & 16 stay tubes renewed & a few C.C. side rivets & C.C. back stays renewed. After repairs both boilers tested to 1 1/2 times the W.P. and found tight & sound. A new donkey boiler as per attached report G.S. No. 36717 has now been securely fitted on board and all connections made.

General Observations, Opinion, and Recommendation: The machinery of this vessel is now in good condition and is in my opinion eligible to remain as classed in the register book with fresh record L.M.C. 5.17.

A.D.B. 17, 100 lbs per sq. in.
This vessel is now fitted with wireless telegraphy.

Survey Fee (per Section 25) £ 5.10.0
 Special Damage or Repair Fee (if any) £ : : :
 Travelling Expenses (if chargeable) £ : : :
 Fees applied for 9 - MAY 1917
 Received by me, George Murdoch 4/6/17
 Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI. 18 MAY. 1917
 Assigned L.M.C. 5.17
N.D.B. 17
 MACHINERY CERTIFICATE WRITTEN 14.6.17
 TUE. 21 AUG. 1917
 FRI. 18 JAN. 1918
 TUE. APR. 9 1918.



S. S. No 3 due 1.16. 1904
in entirety & NDB filled

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

N.B. furnace renewed etc.

It is submitted that
this report is for
THE RECORD. + LMC 5.14

NDB 19.

DB personal 1904

J.M.
14.5.14

[Faint, illegible handwritten text covering the main body of the page, likely bleed-through from the reverse side.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

SIR,

Donkey

(Annan

that th

The Sec
Lloyd



© 2020
Lloyd's Register
Foundation