

of Survey for Repairs, &c., of Engines and Boilers.

No. 15660

MON. 10 OCT. 1923

9th September 1923 When handed in at Local Office (Received at London Office) 10 Port of **HAMBURG**

held at **HAMBURG** Date, First Survey 23rd August 1923 Last Survey 5th September 1923 (No. of Visits 6)

Machinery of the ~~Wood, Iron or Steel~~ Sc. "Sokoto" (extra) Vessel built at **Fumbarton** By whom **St. M. Millan & Son, Ltd.** When **1901-4**
 Engines made at **Kasgow** By whom **Muir & Houston, Ltd.** When **1901**
 Boilers, when made (Main) **1901** (Donkey) **1901**
 Owners **African S.S. Co. (Glder, Empster & Co., Ltd.)** Port **London** Voyage **W. Africa**
 If Surveyed Afloat or in Dry Dock **Afloat** (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Date of last Survey and of Periodical Surveys.	Year and Month when applied.	Machinery and Boiler Surveys (including date of R.B., if any).
<input checked="" type="checkbox"/> 100 A1	1922		<input checked="" type="checkbox"/> L M C 3, 19
S.S. Kam. N ^o 3-2, 11			<input checked="" type="checkbox"/> B S 4, 22
S.S. Sri. N ^o 2-19			T.S. (U.K.) 4, 22

Port **HAMBURG** Examination and Repairs (if any) **A. L. M. C.**

When held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of examinations and subsequent repairs. Repairs on the cause of which must be stated should be separated from repairs due to other causes; and in the body of the report, should be briefly summarised at the end of the report. State also the reasons for any special damage report.

Has the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were not? **Was a damage report made by anyone else? If so, by whom?**

Go inside each Main Boiler separately and make a thorough examination at this time? **yes**
 Donkey " " " " **no**
 For what reasons? **Donkey Boiler not submitted for Survey, was continually under steam.**
 Boilers could not be thus thoroughly examined? **no**
 In the absence of internal examination, were adopted by the Surveyor? **no**
 the Safety Valves of the Main Boiler? **yes** To what pressure were they afterwards adjusted under steam? **160 lbs.**
 the Safety Valves of Donkey Boiler? **no** To what pressure were they afterwards adjusted under steam? **no**

all the manholes, doors and their fastenings of the Main Boilers? **yes**, and of the Donkey Boiler? **no**
 the drain plugs of the Main Boilers? **none**, and of the Donkey Boiler? **no**
 all the mountings of the Main Boilers? **yes**, and of the Donkey Boiler? **no**
 drawn and examined? **no** Is it fitted with continuous liner? **no** Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? **no**
 Has it a continuous liner? **no** Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? **no**

Has the Surveyor examined the stern bush and top of after bearing of screw shaft? **yes**
 State what arrangements have been made for its completion and what remains to be done? **not complete, it is stated by the Surveyor that the Survey will be completed at next opportunity.**

Connections & fastenings to be examined at next dry docking & examination of the Donkey-Boiler.
 Examined I.P. & L.P. cylinders, covers, pistons, slide valves, chests & rods; H.P. & I.P. connecting rods & end brasses; L.P. connecting rod with top end brasses; H.P. & I.P. crankpins, I.P. & L.P. crankshaft bearings, bed plate; the main shaft & block, line of tunnel shafting, condenser, pumps, pipes & connections & up as well as steering engine, the Main Boilers in & externally with no openings opened up, also under Boilers tight & safety valves adjusted to 160 lbs., found all of these parts in satisfactory condition after the had been carried out: St. Boiler starboard comb. chamber back (stay removed); port comb. chamber back & flanging of port lower manhole bottom built up by electric welding; St. Boiler flanging of the 2 lower built up by electric welding. Engine & auxiliaries examined under working conditions & found satisfactory.


Opinion, and Recommendation:—The Machinery of this vessel, as far as seen, is in satisfactory condition & eligible in my opinion to remain as classed in the Society's Register with the Record of "A. L. M. C.—9, 23" subject to the examination of the Donkey Boiler & the Sea connections & fastenings.

Fees applied for 9th Sept 1923 £ 10.0.0
 Received by me, 19 £ 0.10.0

TUE OCT. 9 1923

TUE. 6 NOV. 1923
 FRI. 21 DEC. 1923
 TUE. 1 JAN. 1924
 FRI. 25 JAN. 1924

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W700-0197

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to...

L.S. No 3 due 2.23 partly held on machinery
3.23 advances stated will be completed
at first opportunity. B.S. due 4.23 partly
held.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that this
vessel WILL BE eligible for
the record. + L.M.C. MS 3.23
BB 9.23
when the propeller, and immediately
after fastening have been examined
and B.S. held in its
entirety.

L.
8/10/23

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register
Foundation