

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

THU JUN 10 1920

Report 4 June 1920 When handed in at Local Office

Port of Rotterdam

Survey held at Rotterdam Date, First Survey and East Survey 26-4 1920

on the Machinery of the ~~Wood, Iron or Steel~~ *Western Front* Master *Samuel*

GROSS 5743 Vessel built at *Seattle* By whom *Shinner Lloyds* When 1914

et 4409 Engines made at *Seneca* By whom *General Electric Co.* When 1914

Boilers, when made (Main) *Donkey*

Boilers 4 Owners *United States Shipping Co.* Port *Seattle* Voyage *Maure*

ers *well* If Surveyed Afloat or in Dry Dock *both*

Boilers *Wiltons Dock*

Port No. Port

ars of Examination and Repairs (if any) *T.S. sur*

veys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the

uses where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were

not required Was a damage report made by anyone else? If so, by whom? *Unknown*

or personally go inside each Main Boiler separately and make a thorough examination at this time? *✓*

Donkey " " " *✓*

done, state for what reasons? *✓*

of the Boilers could not be thus thoroughly examined? *✓*

al means, in the absence of internal examination, were adopted by the

or examine the Safety Valves of the Main Boiler? *✓* To what pressure were they afterwards adjusted under steam? *✓*

or examine the Safety Valves of Donkey Boiler? *✓* To what pressure were they afterwards adjusted under steam? *✓*

or examine all the manholes, doors and their fastenings of the Main Boilers? *✓* and of the Donkey Boiler? *✓*

or examine the drain plugs of the Main Boilers? *✓* and of the Donkey Boiler? *✓*

or examine all the mountings of the Main Boilers? *✓* and of the Donkey Boiler? *✓*

ft now been drawn and examined? *Yes* Is it fitted with continuous liner? *Yes* or two liners? *✓* or is it without liners? *✓*

been changed? *No* If so, state reasons *✓*

ow fitted new? *✓* Has it a continuous liner? *✓* or two liners? *✓* or is it without liners? *✓*

nce between lignum vitae of stern bush and top of after bearing of screw shaft? *1/4" lignum vitae renewed.*

not complete state what arrangements have been made for its completion and what remains to be done? *This vessel is reported to have*

aground in Ghent canal, on her last voyage.

placed in Dry Dock, screw shaft drawn examined and found in good

ition, lignum vitae renewed. Propeller, sternbush and fastenings good. See

tions and fastenings good.

Observations, Opinion, and Recommendation:—

only what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also

alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,11, B.&M.S. 9,11, or L.M.C. 9,11

machinery of this vessel being now in good and efficient condition

of opinion that she is eligible to remain as classed with fresh

of T.S. sur 5.22.

Section 29) £ 25.00 Fees applied for

or Repair Fee (if any) £ : : 16 1920

Section 29) £ : : Received by me,

expenses (if chargeable) £ : : 16 1920

tee's Minute

d

FRI JUN 18 1920

FRI AUG 19 1921

ERI AUG 16 1920

TUE MAY 31 1921

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

10718-0141

Is a Certificate required? If so, to be sent to

Damage due to grounding.
Screw shaft, propeller & sea
connections examined.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain as CLASSED.

54.20.

For
16/6/20.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation