

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

SAT.-8 APR. 1916)

Date of writing Report 6 APR 1916 When handed in at Local Office 6 APR 1916 Port of LIVERPOOL

No. in Reg. Book. Survey held at Birkenhead Date, First Survey 9 Last Survey Mar 31 1916

213. on the Machinery of the Wood, Iron or Steel S. Gent. Master Martin

Tonnage Gross 3890 Net 2485 Vessel built at Belfast By whom Workman Black & Co When 1905. 6.

Registered Horse Power 577 Engines made at Boilers, when made (Main) 1905. (Donkey) -

No. of Main Boilers 4 Owners Elders & Fyffes Port Belfast Voyage Santa Marta

No. of Donkey Boilers - Steam Pressure in Main Boilers 190 If Surveyed Afloat or in Dry Dock Bkn. DDK

in Donkey Boilers - Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. Port

Particulars of Examination and Repairs (if any) Dkg.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. Donkey

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Has screw shaft now been drawn and examined? no Is it fitted with continuous liner? or two liners? or is it without liners?

Has shaft now been changed? If so, state reasons

Is the shaft now fitted new? Has it a continuous liner? or two liners? or is it without liners?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? 1 1/4

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

Propeller + fastenings of sea connections examined in drydock.

One bent bronze propeller blade now renewed.

General Observations, Opinion, and Recommendation: This vessel's machinery, as far as seen, is in good working order + eligible to remain as classed.

Survey Fee (per Section 29) £ 19

Special Damage or Repair Fee (if any) (per Section 29.) £

Travelling Expenses (if chargeable) £

Fees applied for Received by me, 19

A. J. Barnett, Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute LIVERPOOL - 7 APR 1916 TUE. 11 APR. 1916

Assigned as now

Lloyd's Register Foundation

W724 - COH



It is submitted that  
this vessel is eligible to  
remain as **CLASSED**.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

JP  
10.4.16

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register  
Foundation