

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... 20-12-11 Port of GRIMSBY

No. in Reg. Book... Survey held at GRIMSBY Date, First Survey 11-12-11 Last Survey 18-12-1911

9 Sup. on the Wood, Iron or Steel S. H. SKULLI FOGETI. Master H. H. Thorsteinsson

TONNAGE:- Built at Selby. By whom Cochrane Hows When 1911.

GROSS 225 Owners Fiskiveidalafjelagid. Alliance. Port belonging to Reykjavik.

UNDER DEK. Owners' Address

NET (if not already recorded in Appendix to Register Book). Name of Dock Alexandra Wet. Destined Voyage Reykjavik.

Surveyed Afloat or in Dry Dock? WB=CellDBorDBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined. If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined.

Last Report, No. Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements). CHARACTER. 100 A1. Ship, Trawler (Class Contemplated).

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of 1st. Entry, as requested by letter from the Hull Surveyors Nov. 30th/11.

The engines and boiler placed on board and secured in position, the boiler casing with 2 fidley latches, boiler room ventilators, engine room skylight, and main funnel, afterwards fitted on board and securely riveted in place. The deck plating port and stbd, in way of casing riveted up, and the wood deck in way of same laid, calked, and payed. Deck pumps tested.

Rigging fitted of the following ropes:- Foremast:- 3 Shrouds each side 3" steel wire. Topmast Stay 2 1/4", forestay 3 3/4", 2 fore preventer stays 2 3/4". Steel wire. Mizzen Mast:- 2 Shrouds each side 2 1/4", 2 forestays 2 1/4", 2 backstays 2 1/4". Steel wire.

SUMMARY OF DAMAGE REPAIRS:- Table with columns: Plates, Frames, R. Frames, Floors, Beams, Str. Plates, Dk. Plates, Other Items:-

PRESENT CONDITION OF THE Table with columns: Decks, Caulking of Decks, Waterways, Coamings, Beams & Fastenings, Outside Plating, Caulking of ditto, Rivets, Breasthooks & Crutches, Transoms, Frames, Reverse Frames, Floors, Keelsons, Stringers, Inner Bottom Plating, State if Tanks have been examined inside, State if Tanks now tested, Bulkheads, Ceiling, Cement or Asphalt, Rudder, Steering gear and its connections, Have Pumps now been examined and found efficient?, Have Sluice Valves now been examined and found efficient?, Have Watertight Doors now been examined and found efficient?, Dbing. Plates under Sounding Pipes, Engine Room Skylights, Coal Bunkers, Open'gs, Lids, &c., Scuppers, Cargo Hatchways, Hatches, Planking of Wood Vessels, Caulking, Treenails, Breasthooks & Stemson, Transoms, Pointers, & Crutches ditto, Timbers of Frame at openings ditto, Ditto ditto at other places ditto, Stringers, Clamps & Shelves ditto, Salting, Copper, or Y.M. of Wood Vessels, Boats, Masts, Yards, &c., Condition, how ascertained, Sails, Equipment letter, Anchors, No. of, Cables, Hawser & Warps, Standing & Running Rigging.

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:-

This report is forwarded for the information of the Committee.

Survey Fee (per Section 29) £... Fees applied for, 19... Received by me, 19... Robt. Cheetham. Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute TUE. JAN. 2-1912 Character Assigned su Minute on Hull 7-E. Rpt 24526