

Report of Survey for Repairs, &c., of Engines and Boilers. No. 76191

Date of writing Report 16 MAR 1917 When handed in at Local Office 16 MAR 1917 Port of LIVERPOOL

Survey held at Birkenhead Date, First Survey Mar 7th Last Survey March 15th 1917
 on the Machinery of the Wood, Iron or Steel S. Wapello Master
 Vessel built at Newcastle By whom Atkinson, Whitworth & Co. When 1912
 Engines made at " By whom R. E. Mas. Eng. Co. Ltd When 1912
 Owners W. J. Smith Mgrs Port London Voyage
 If Surveyed Afloat or in Dry Dock Birkenhead Dk. (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 CHARACTER: 100A1-8-16
 Machinery and Boiler Surveys: Class 8.16
 Carrying Petroleum Bulk
 S.S. 101-16

Special Surveys, when held, must be reported in detail and certaintly in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and the names and initials of any letters respecting this case.
 Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? *Not required* Was a damage report made by anyone else? If so, by whom? *None*
 Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?
 Do. " " Donkey " " " "
 Was this not done, state for what reasons?
 What parts of the Boilers could not be thus thoroughly examined?
 What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
 Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?
 Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?
 Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boiler?
 Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?
 Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?
 Has the screw shaft now been drawn and examined? *yes* Is it fitted with continuous liner? *yes* or two liners? or is it without liners?
 Has the shaft now been changed? *yes* If so, state reasons *To be dressed up + kept as spare*
 Has the shaft now fitted new? *yes* Has it a continuous liner? *yes* or two liners? or is it without liners?
 Is the distance between lignum vitae of stern bush and top of after bearing of screw shaft? *3 3/4*

Survey is not complete state what arrangements have been made for its completion and what remains to be done? *Complete*
 Damage due to the loss of the propeller nut, and the propeller becoming loose while going astern when off the Bar Lightship on March 3rd 1917 while outward bound.

Upon examination in the drydock it was found that the four bladed solid cast-iron propeller was hanging on the end of the shaft against the rudder post; the tips of all the blades were broken on the after side. The tailshaft ^{has been} removed, examined in the lathe & found to be quite true, the astern side of the keyseat is slightly damaged & the key bent, and screw threads buried (4) at the forward end. This shaft is to be skimmed up, keyway dressed up, rethreaded & a new nut & pin fitted & kept as a spare. The new spare tailshaft ^{LLOYD'S J.F.B. 5/12/11} & a new propeller has now been fitted.

General Observations, Opinion, and Recommendation:— This vessel's machinery is as far as seen is in good working order & eligible to remain as classed & to have fresh record of N 28 3.17

Fee (per Section 28) £
 Damage or Repair Fee (if any) (per Section 29.) £ 2.2.0
 Other Expenses (if chargeable) £
 Fees applied for 16 MAR 1917
 Received by me, A. J. Barrett, 21.3.17
 Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute LIVERPOOL 16 MAR 1917
 Signed As now note J.S.



Insert Character of Ship and Machinery precisely as in the Register Book.

In a Certificate required? If so, to be sent to

Propeller & Shaft renewed
for damage through stacking back
of propeller

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain as **CLASSED**,

N.S. 3.14

[Signature]
19.3.14

[Faint, illegible handwriting in the main body of the document, likely bleed-through from the reverse side.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation