

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office. MAR 13 1940)

Date of writing Report 7-3-40 When handed in at Local Office 11-3-40 Port of Glasgow  
No. in Reg. Book. Survey held at Glasgow Date, First Survey Jan 25 Last Survey 7-3-1940  
33300 on the Machinery of the Wood, Iron or Steel S.S. "SCHOLAR" (No. of Visits 9)

Tonnage { Gross 3940 Vessel built at Glasgow By whom C. Connell & Co. Ltd. Year. Month. 1922 6  
Net 2473 Engines made at Glasgow By whom Dunsmuir Jackson When 1922  
Nominal Horse Power 390 Boilers, when made (Main) 1922 (Donkey) -  
No. of Main Boilers 353 Owners Chartered S.S. Co. Ltd. Managers' Address Port, Liverpool Voyage -  
No. of Donkey Boilers - Managers J. J. Harrison (if not already recorded in Appendix to Register Book.)  
Steam Pressure in Main Boilers 215 lb. If Surveyed Afloat or in Dry Dock Both Meadowside & R. Guel Kelvin Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Cast Report No. - Port -  
Particulars of Examination and Repairs (if any) Docking M.S.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom? -

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? No  
If this was not done, state for what reasons? B.S. not due

And what parts of the Boilers could not be thus thoroughly examined? -

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -

State latest date of internal examination of each boiler - Present condition of funnel(s) -

Did the Surveyor examine the Safety Valves of the Main Boiler? - To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine the Safety Valves of Donkey Boiler? - To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? - and of the Donkey Boilers? -

Did the Surveyor examine the drain plugs of the Main Boilers? - and of the Donkey Boilers? -

Did the Surveyor examine all the mountings of the Main Boilers? - and of the Donkey Boilers? -

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

Has shaft now been changed? - If so, state reasons - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

Has the shaft now fitted been previously used? - Has it a continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

State date of examination of Screw Shaft - State the distance between lignum vite or bearing metal of stern bush and top of after bearing of screw shaft 3/16  
Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted? Yes

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? -  
Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? -

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete


NOW DONE.  
Vessel placed in dry dock, after end of stern tube, propeller, under water sea connections and their outside fastenings examined and found or placed in good order

FOR M.S.  
All main engine cylinders, piston, valves and valve casings, crosshead pins and brasses, crank pins and bushes, crank journals and main bearings, thrust, tunnel shafting, dynamo engine, steering engine, reversing engine, air feed, circulating, ballast, general service, (see follow sheet)

General Observations, Opinion, and Recommendation: The machinery of this vessel  
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, E.S.M.S. 9,11, L.M.C. 9,11, or any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.)  
so far as now seen is in efficient condition and eligible in our opinion to remain as classed and to have fresh record  
L.M.C. 140 lb., F.D., &c.  
L.M.C. CS 24,  
L.M.C. MS 3,40

Survey Fee (per Section 20) M.S. £ 8 : - : - Fees applied for 12 MAR 1940  
ELECTRICAL SURVEY. £ 1 : - : -  
Special Damage or Repair Fee (if any) (per Section 20.) £ : : -  
Travelling expenses (if chargeable) £ 2 : 2 : - Received by me, W. Russell R.I. Hurchison  
19

Committee's Minute GLASGOW 12 MAR 1940  
Assigned -1- L.M.C. MS 3,40  
CERTIFICATE WRITTEN



Insert Character of Ship and Machinery precisely as in the Register Book

S. S. "SCHOLAR"

For M.S. con'd.

bilge and sanitary pumps, condenser (tested) and pumping arrangement examined and found as placed in safe working condition. Main and aux. steam pipes tested to rule requirements.

## REPAIRS.

Ballast pump water end renewed, steam cylinders bored out pistons and valves renewed; circulating pump spare impeller fitted.

P. H.

Electrical installation examined under working conditions. Generator cables fittings on main switch board, distribution boxes examined. Insulation tests made on all circuits. All found or put in order. Minor repairs effected.

P. H.

acted  
259  
1873/40

BRITISH MUSEUM

Georgel

BRITISH MUSEUM

Handwritten text, likely bleed-through from the reverse side of the page.

BRITISH MUSEUM

Handwritten text, likely bleed-through from the reverse side of the page.

BRITISH MUSEUM

Handwritten text, likely bleed-through from the reverse side of the page.



© 2020

Lloyd's Register Foundation