

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 7/9/14 19 When handed in at Local Office 7/9/14 19 Port of Vancouver.

No. in Survey held at Vancouver & Victoria Date, First Survey July 20th Last Survey August 20th 1914  
Reg. Book. on the Wood, Iron or Steel Sck "ONWARD HO" Master H. Frederickson.

264 TONNAGE: Built at Hull By whom Earle's Co., Ltd. When 1907 3  
GROSS 338 Owners British Columbia Packers' Association Port belonging to Vancouver.  
UNDER DE. 280 Owners Address  
NET 156 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Slipway Name of Dock Wallace Shipyards Destined Voyage B.C. Coast Fishing.  
VB=CellDBorDBa feet; uE&B feet; f & Yarrows Ltd  
Total capacity tons; FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 425 Port M.V.O.

Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. For Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned. Machinery and Boiler Surveys (including date of N.B., if any).

+100 AI Nwc  
Stm Trawler  
7.13 4.14  
M. 1-11  
+LMC 3,11  
B.S. 6,13  
T. 1.14

Society's Freeboard (if assigned) as painted on Ship and now verified

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?

Was a damage report made by anyone else? If so, by whom? Society, now forwarded.

Repairs, OR EXAMINATION AS PER RULE, FOR stranding at Monte Video May 30th, 1914, while on passage out from England to Vancouver, and completion of oil fuel installation.

Done, - Damage repairs:- Shell Plating, Port side, No. Shell plate in A. Strake renewed.  
No. 9 plate in B. Strake renewed, No. 8 plate in C. Strake renewed, and No. 9 plate faired in place. Starboard side, - Nos. 2 & 6, plates in A. Strake faired in place. Nos. 4, 5 & 6, plates in B. Strake faired in place, and No. 8, plate removed, faired and replaced.  
Nos. 6 & 7, plates in C. Strake faired in place, and No. 8 plate removed, faired, and replaced.  
Four frames and floors in way of the damage on the port side faired, in place, and eight frames and floors in way of the damage on the starboard side faired in place.  
The angle bars at the forward and after ends of the bulkheads of the Oil bunker re-riveted, and a bracket renewed on the starboard side aft. P.T.O.

DESCRIPTION OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed	3							
Removed and Faired or Repaired	2							
Faired or Repaired in place	8	12		12				

CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks have been examined inside	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder	Steering gear and its connections	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?
Good	Good				Good		Good				Yes.		
of Decks	"												
ys	"												
s	"												
Fastenings	"												
Plating	"												
of ditto	"												
ks & Crutches													
Good													
frames	"												
"													
"													

DOUBLE PLATES UNDER SOUNDING PIPES	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Caulking	Treenails	Breasthoeks & Stemson	Transoms, Pointers, & Crutches	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shells	Salting (State if examined.)	Copper, or Y.M. of Wood Vessels (State if on Felt.)	When put on, Month	Year	Boats	Masts, Yards, &c.	Condition, how ascertained (State if wedges removed)	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	length (on board) size	Rule length size	Hawser & Warps	Standing & Running Rigging
	Good																											

## General Observations, Opinion as to Class, Recommendation, &amp;c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon a survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 11," or "to remain as classed and to have record of survey, 1, 11, and the notations of ss No. 1-11 and ptND11, &c."

This vessel being in good and efficient condition she is eligible in my opinion to be continued as classed without fresh record of survey 8, 14 Ver. and to have the notation tail shaft seen 8, 14.

(per Section 29)	£	:	:	Fees applied for,
Damage or Repair Fee (if any) (per Sec. 29)	17	:	0	5/9 1914
Ring Expenses (if chargeable)	10	:	0	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute

Character Assigned

FRI. OCT. 2. 1914

Stm Trawler

Link for oil fuel  
T.P. Alms 150 ft.

W808-0161

© 2021

Lloyd's Register  
Foundation



Now done:- The ceiling removed from on top of the floors, the temporary openings in the after bulkhead of the oil fuel tank permanently closed by steel plates, fitted, riveted and caulked. The oil tanks tested to classification requirements and made tight, and all the requirements of Section 49 of the Book of Rules complied with. The oil fuel has a flash point of above 150° F.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

[illegible]

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]