

S. S. OHIO Contd

Repairs - 12 loose bedplate chocks renewed. (C.I.) L.P. bottom end bushes remitted. H.P. valve chamber bored out, new rings fitted in piston valve. H.P. piston rings renewed. A new feed donkey has been fitted on board, and tested on boilers. New bilge injection valve fitted. Ballast pump buckets, and liners renewed. 38 tank and bilge valve spindles (steel) renewed (brass spindles fitted.)

Boiler repairs - A number of tubes expanded. A number of smoke box studs renewed in boiler ends. Internal feed and blow down pipes repaired.

Thomas W. C. Napier

M.B. - If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

New shaft due 12.16 now examined
& machinery examined
New shaft fitted

NS 1.17.

J.W.D.
17/1/17.



© 2020
Lloyd's Register
Foundation