

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office TUE SEP. 22 1914)

Date of writing Report 19 When handed in at Local Office 21.9.1914 Port of Grimsby

No. in Reg. Book. 365 Survey held at Grimsby Date, First Survey and Last Survey 16.9.1914

on the Machinery of the Wood, Iron or Steel Sc. K. MANX QUEEN Master (No. of Visits)

Tonnage { Gross 219 Net 117 Vessel built at Selby By whom Cochrane & Sons When 1906-9

Registered Horse Power 67 Engines made at Hull By whom C.D. Holmes & Co. When 1906

No. of Main Boilers 1 Boilers, when made (Main) 1906 (Donkey)

No. of Donkey Boilers 1 Owners W.A. Beeley Port Grimsby Voyage Fishing

Steam Pressure in Main Boilers 180 If Surveyed Afloat or in Dry Dock Fish

in Donkey Boilers

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. Port

Particulars of Examination and Repairs (if any) Dry etc etc.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

CHARACTER. for Special Survey. Date of last Survey and of Periodical Surveys.	Year Assigned how expired.	Machinery and Boiler Surveys (including date of N.B., if any).
-1-100 A1 Stm Trawler 6.14 S.S. Gms No 2-14		-1-L.M.C.6.14 S. 6.13.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " " "

If this was not done, state for what reasons?

B.S. not due.

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Has screw shaft now been drawn and examined? yes Is it fitted with continuous liner? yes or two liners? or is it without liners?

Has shaft now been changed? No If so, state reasons

Is the shaft now fitted new? Has it a continuous liner? or two liners? or is it without liners?

State the distance betweenignum vitæ of stern bush and top of after bearing of screw shaft? 1/8

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Now Done :- Vessel placed in dry dock; Screw shaft, propeller, stern bush and fastenings examined; new propeller fitted.


General Observations, Opinion, and Recommendation:— The Machinery of this vessel is eligible, in my opinion, to remain as classed, and to have fresh record of Screw shaft last seen 9.14.

Survey Fee (per Section 28)..... £	Fees applied for
Special Damage or Repair Fee (if any)..... £	
Travelling Expenses (if chargeable)..... £	

G. J. Johnson
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI. SEP. 25. 1914

Assigned as now



Propeller renewed & shaft
exam^d

It is submitted that
this vessel is eligible to
remain as CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

59.17

SP

22-9-14

[Faint, illegible handwritten text, likely bleed-through from the reverse side of the page.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation