

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

FRI. FEB. 16. 1912

Date of writing Report 15/2/12 When handed in at Local Office 15.2.12 Port of Gool

No. in Reg. Book 1095 Survey held at Gool Date, First Survey Jan 24 Last Survey 10/2/12 19

1095 on the Machinery of the Wood, Iron or Steel S. S. Humber Master A. Th. Thillan

Tonnage Gross 1023 Net 490 Vessel built at Dumbarton By whom A. Th. Thillan

Registered Horse Power 229 Engines made at P. Glasgow By whom Blyde & Co. When 1903

No. of Main Boilers two Boilers, when made (Main) 1903 (Donkey) ✓ When 1903

No. of Donkey Boilers ✓ Owners Lancashire & Yorkshire R. Co. Port Gool Voyage

Steam Pressure—180 If Surveyed Afloat or in Dry Dock Gool (State name of Dock.)

in Main Boilers ✓ in Donkey Boilers ✓

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned and expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>+100 A 311</u>		<u>+2 Th. 6. 10. 07</u>
<u>1. 9. 00 21-07</u>		<u>13. 1. 3. 11</u>

Last Report No. Port

Particulars of Examination and Repairs (if any) B. & Damage

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? yes

To what pressure were they afterwards adjusted under steam? 185

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓

To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes

, and of the Donkey Boiler? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? yes

, and of the Donkey Boiler? ✓

Did the Surveyor examine all the mountings of the Main Boilers? yes

, and of the Donkey Boiler? ✓

Has screw shaft now been drawn and examined? yes

Is it fitted with continuous liner? no or two liners? no or is it without liners? yes

Has shaft now been changed? no If so, state reasons ✓

Is the shaft now fitted new? metal

Has it a continuous liner? ✓

or two liners? ✓

or is it without liners? ✓

State the distance between metal of stern bush and top of after bearing of screw shaft? Bush re-metalled a good fit

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete

How done on account of damage through chuck cover blowing off & consequent pounding.

Screw shaft drawn in & bush re-metalled, air pump rod renewed, all pumps & condenser, & screw shaft fastenings examined, boilers opened out & examined tubes expanded, H.P. piston rod skimmed up, after life pump cam repaired feed check valves renewed.

Main boilers examined internally & externally, all feed checks renewed fifteen lower tubes in both centre boxes renewed, all tubes expanded, corners of furnaces (studs) side of both centre chambers where riveted to wrapper plates built up by oxy-acetylene & riveted. Safety valves adjusted as above.

H.P. piston, rod & cylinder examined & renewed & the tube taken as per L.H.C. also pumps & condenser.

General Observations, Opinion, and Recommendation:— The Machinery of this vessel as
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 3,00, B.&M.S. 3,00, or L.M.C. 3,00, 140 lb., F.D., &c.)

far as now seen is in good safe working condition & in my opinion eligible for the record B. & 2, 12. S. 2, 12 to be noted.

Survey Fee (per Section 28) £ 1 : 10 : 0 Fees applied for 15.2.12

Special Damage or Repair Fee (if any) £ 2 : 2 : 0 NR

(per Section 28.) £ 7 : 0 : 0 Received by me, 28.3.12

Travelling Expenses (if chargeable) £ 3 : 16 : 0

TUE. FEB. 20. 1912

Committee's Minute

Assigned

Frank A. Lingen
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2020

Lloyd's Register
Foundation

W856-0161