

LONDON BRITISH & COLONIES

BENEFICIAL DOCK WITH PLATES

REMOVED FROM VESSEL.

DUBLIN

28th. March 1916

BENEFICIAL DOCK WITH PLATES

No. 1. Indented.

Partly Uprivet and fair in places.

No. 2. Nearly indented.

Remove, fair and refit.

No. 3. JOHN MACWILLIAM Partly Uprivet and fair in places.

BENEFICIAL DOCK WITH PLATES

the Owners Representative on the 28th. March 1916, examining the
 S.S. "LADY OLIVE" 701 Tons Gross Register, J. Cannell, Master,
 whilst in the Graving Dock here, in which dry-dock the vessel
 had been placed for the purpose of ascertaining:-

1st. HULL. The damage stated to have been sustained in July
 last by the vessel colliding with Fender Piles at
 Southampton, whilst making that Harbour during bad
 weather. For particulars see Ships Log Books.

2nd. MACHINERY. It is stated that this vessels tail shaft
 had during the month of February 1916 caused trouble by
 running hot in the stern stuffing box and its gland,
 necessitating the reduction of revolutions and of
 continuous cooling from the water service, no water
 finding its way from the sea through the stuffing box.
 In case of damage, set in.

DAMAGE

Fwd. end of bottom, partly

HULLFWD SIDERECOMMENDATIONS

© 2020

Lloyd's Register
Foundation

(2)

DAMAGE	RECOMMENDATIONS
Forecastle Deck Side plating Plates Numbered from Stem. First Strake below.	Repair as necessary and fair and rivet.
<u>FORECASTLE SHEER STRAKE</u>	
No. 3. Indented.	Partly Unriveted and fair in place.
" 2. Badly indented.	Remove, fair and refit.
" 4. Indented.	Partly Unriveted and fair in place.
Set up defective rivetting in and botto, about 300, fair and rivet.	
<u>First Stroke Below Sheer</u>	
No. 1. Indented.	Partly Unriveted and fair in place.
" 2. Badly indented.	Remove, fair and refit.
" 3. Badly indented.	Partly Unriveted and fair in place.
Upper edge of Main Sheer Strake, set in.	Repair in place.
4 Frames in way of above, set in.	Fair in place and rivet.
Bending iron in way of above, set in.	Remove to nearest butts, fair and replace about Twenty Feet.
R.C. stringer plate and in way of damage, set in.	Partly Unriveted, fair and rivet for about Ten Feet.
Belting around end of belting, more or less set in in three strakes.	Fair and refit.
	Partly Unriveted as necessary and fair the three 200 plates and rivet.



Lloyd's Register
Foundation

(3)

DAMAGERECOMMENDATIONSSTEM PLATING & STEM

2 Stem Plates, P & S, the second stroke below Main Sheer, slightly indented and rivetting started.

Partly Unrivet fair and rivet. Set up all started rivetting as necessary and recaulk.

FORE PEAK TANK

Shell rivetting more or less in the half shaft being drawn started on both sides.

The Fore Fwd and Stern gland were found damaged the lining being parted near its forward end and the gland bushing damaged.

Set up defective rivetting in seam and butts, about 300. Pare and recaulk edges and butts of same, about 60 Feet as necessary and replace very defective rivets where necessary. Retest tank.

It is stated that on the vessel being docked the space between the propeller and the stem bulkhead fore end of No. 1. Ballast tank, was riveted.

Renew defective rivetting in Port and Starboard Sides as necessary (about 18). Test Ballast Tank.

Pare and recaulk adjacent seams as necessary.

All as per recommendations.

and Machinery is as good condition as before damage.

Two Keel plate butts, aft, slightly, started.

Pare and caulk butts as necessary.

One length of Bilge Keel, Port Side, buckled.

Recommendation
Remove about Twenty-six Feet and Surveyor to lay in Register fair and refit.

Set up shell rivets in way of some as necessary, about forty rivets.



Lloyd's Register
Foundation

W8158-0122(314)

