

good working order.

The main boilers examined in their entirety, put in good condition and their safety valves adjusted under steam.

Port Boiler

Front circumferential seam in way of port furnace 22 rivets caulked & landing edge, also 10 rivets in way of Starboard furnace caulked together with landing edge. One rivet caulk in circumferential seam at back end of boiler shell.

Starboard Boiler

Front circumferential seam in way of port furnace 10 rivets caulked & landing edge, also 6 rivets in way of starboard furnace caulked together with landing edge, also port and Starboard furnace mouths landing edges caulked & rivets where necessary.

Spigot at back end of boiler shell caulked in way of blow down valve.

N.B. - If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Machinery & boilers examined
& repairs effected

It is submitted that
this vessel is eligible to
remain as UNCLASSIFIED.

13.5.18.

13.6.18.



© 2020

Lloyd's Register
Foundation

OF THE SERVICES ARE REQUIRED FOR TO THE SHIP AND THE SHIP.