

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office APR 22 1940)

Date of writing Report 1940, When handed in at Local Office 15/4/40 Port of TRIESTE

No. in Reg. Book. Survey held at TRIESTE Date, First Survey Mar 29 Last Survey Apr 8 1940 (No. of Visits four)

35/43 on the Machinery of the Wood, Iron or Steel S.S. "TIMAVO" (P).

Tonnage { Gross 7549 Vessel built at Trieste By whom Cantiere San Rocco S.A. When 1920.8
Net 4731 Engines made at Trieste By whom Stab. Tecnica Triestina When 1920

Nominal Horse Power { 68 Boilers, when made (Main) 1920 (Donkey) ✓

No. of Main Boilers 450 Owners Lloyd Triestino Soc. Anon. Owners' Address (if not already recorded in Appendix to Register Book.)
Managers di NAV. Port TRIESTE Voyage ✓

No. of Donkey Boilers ✓ If Surveyed Afloat & in Dry Dock Both (State name of Dock.) Arsenale Triestino

Steam Pressure in Main Boilers 180 lbs. in Donkey Boilers ✓

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. for Special Survey Date of last Survey and of Periodical Surveys.	Years assigned for survey.	Machinery and Boiler Surveys (including date of N.B., if any).
+10091. S.M.T. 4K.		+ L.M.C. 4-37
with freeboard		BS. 5-39.
5-39.		+ Lloyd's R.M.C.
SS Gln N°3. 12-32		5-39.
SS Tri. N°1. - 37.		CL. 9-38

Last Report No. Port

Particulars of Examination and Repairs (if any) Docking, BS.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes ✓

" " Donkey " " " " ✓

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler. Starb. fwd. & aft. 2.4.40. Port fwd. & aft. 5.4.40 Present condition of funnel(s) Good

Did the Surveyor examine the Safety Valves of the Main Boilers? yes To what pressure were they afterwards adjusted under steam? 180 lbs/10" ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? yes and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft ✓ State the distance between lignum vitae or bearing-metal of stern bush and top of after bearing of screw shaft 4 1/2" ✓

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted ✓

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Now Done for BS. Examined the main boilers (4) internally & externally, together with all mountings and doors. All safety valves adjusted under steam to 180 lbs/10". Examined and tested all deck control gear for oil fuel daily service tank valves and steam to oil fuel pumps. Oil fuel burning installation examined under working conditions and found satisfactory.

Repairs: Starb. aft. boiler - 2 C.O. stays renewed. Bottom manhole doors (2) built up by welding and refitted.

Port aft. boiler - Centre cc. Some rivets in furnace flange renewed. Now Done for Docking. Vessel placed in drydock. Examined propeller, aft end of stern bush and fastenings of all underwater connections. All found & placed in good condition.

General Observations, Opinion, and Recommendation: The machinery of this vessel, so far as now seen, is in good condition and eligible in my opinion to remain as classed with free record BS. 4-40.

Survey Fee (per Section 29) BS. 465- Fees applied for 20/4/40
Special Damage or Repair Fee (if any) (per Section 29) £ 20- Received by me, 19
Travelling expenses (if chargeable) £ 40-
Sunday & Committee's Minute 14.40
Assigned

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

W90-0168

BS due 5.40 Held
Several Cont. Chamber Flays and
rivets in furnace flays removed

It is submitted that
this vessel is eligible for
THE RECORD.

BS 4.40

Hum
29. 4. 40



© 2020

Lloyd's Register
Foundation