

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report. 10 Dec.

1912 When handed in at Local Office.

10 Dec.

1912

Port of

SUNDERLAND.

No. in Survey held at
Reg. Book Supplement.

54. on the Wood, Iron or Steel sc. sr. "Ethel Duncan"

Date, First Survey

31 Oct.

Last Survey

9 Dec. 1912

(No. of Visits)

Master A.R. Murphy 1909

1912

TONNAGE:-

GROSS 2510

UNDER D.K. 1832

NET 1091

Built at Alloa.

By whom Mackay Bros.

When 1912.

Owners J.T. Duncan & Co.

Port belonging to Cardiff

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Both. Name of Dock No. 1 Dry D.

Destined Voyage Strazaire.

WB=Cell DBor DBa feet; uE&B feet; f feet; t tons.

total capacity tons. FPT tons; APT tons; MT feet tons.

N.B. - All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No.

Port

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Years assigned, exp'd.	Machinery and Boiler Surveys (including date of N.B., if any).
+100 A1 (Class Contemplated)		

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Yes - not required Was a damage report made by anyone else? If so, by whom? Mr Metcalf for Underwriters

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage and Completion of Survey for Classification

Damage, stated to have been caused (a) on 29 Oct 1912 through the vessel striking the dock wall whilst she was entering the So. Dock Sunderland (b) on 25 Nov 1912 through being struck by whilst lying in the So. Dock Sunderland by the steamer "Rolandseck" (c) on 25 Nov 1912 through being struck whilst lying in the So. Dock Sunderland by the steamer "Mari Menzel nowdone. (a) shellplating & framing on starboard side in machinery space - F shake N: 8 from fore end removed, faired & replaced

G N: 8

2 frames faired in place. To effect these repairs vessel was placed in dry dock.
Bottom & under examined & coated

SUMMARY OF DAMAGE REPAIRS:-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired	3							
Faired or Repaired in place	2	3						

PRESENT CONDITION OF THE Decks	good	Dblng. Plates under Sounding Pipes	good	Copper, or Y.M. of Wood Vessels
Caulking of Decks	good	Engine Room Skylights	good	(State if on Felt.) When put on, Month Year
Faterways	good	Coal Bunkers, Open'gs, Lids, &c.	good	Boats
Seamings	good	Scuppers	good	Masts, Yards, &c.
Beams & Fastenings	good	Cargo Hatchways	good	Condition, how ascertained
Outside Plating	good	Hatches	good	(State if wedges removed) no
Bulkling of ditto	good	Planking of Wood Vessels	good	Sails
Wets	good	Caulking	ditto	Equipment letter
Basthooks & Crutches	good	Treenails	ditto	Anchors, No. of 38 15 1K
Nsons	good	Breasthooks & Stemson	ditto	Cables (State if now ranged) no
mes	good	Transoms, Pointers, & Crutches	ditto	" length (on board) size
verse Frames	good	Timbers of Frame at openings	ditto	" Rule length (per Table 22) size
ts	good	Ditto ditto at other places	ditto	Hauser & Warps
Bons	good	Stringers, Clamps & Shelves	ditto	Standing & Running Rigging
		Salting (State if examined)	ditto	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,09," or "to remain as classed and to have record of survey, 1,09, and the notations of ss No. 1-09 and pTND09, &c."

This report is forwarded for the information of the Committee as regards the work nowdone the vessel is eligible in my opinion to receive the class contemplated.

Fee (per Section 28)	£	: : :	Fees applied for	
Damage or Repair Fee (if any) for Sec. 28)	£	3 : 3 : 0.	14.12.1912	1/2 1/2 1/2
ng Expenses (if chargeable)	£	: : :	Received by me	
Surveyor's Fee (if any)	£	: : :	7/3/13	8/8

Surveyor to Lloyd's Register of British & Foreign Shipping.

TUE JAN 11 1913

TUE DEC 17 1912

mittee's Minute

36 Character Assigned Ill Minster on Rte. 7. E. Rpt

13858

Total No. of Visits

Is certificate received? If so, to be sent

© 2020



Lloyd's Register Foundation

MON. DEC 16, 1912

10 Dec 12 on the

steel sc. sr. "Ethel Duncan"

Damage report continued:-

now done (b) to plating rc on starb. side at fore end of bridge

No 1 bridge deck sheers take faired in place -

one bulwark plate faired in place & wash port door repaired

1 length of bulwark rail bar + 2 lengths of moulding removed, faired & replaced.

Bridge front shoe bar faired in place.

now done. (c) to plating rc of bridge sides - starb. side.

(from former) No. 2 Bridge sheers take removed faired & replaced.

two moulding bars removed faired & replaced.

1 frame faired in place.

1 beam knee re-welded

Woodwork in berths renewed where necessary

Completion of Survey for Classification.

now done:— Chain locker flooded & found tight.

Wench deck tanks tested, also fresh water tanks at break of quarterdeck — found same tight.

Decks flooded also waterways & found satisfactory

Tunnel top flooded & found tight

W. S. doors (4) worked & found in good condition

Sewage pump (5) tried on end compartments & found in good order

Hand pump (4) tried & found working satisfactorily

A.M.M.