

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19..... When handed in at Local Office 19..... Port of Auckland
 No. in Survey held at Auckland Date, First Survey 17/4/07 Last Survey 20/4 - 1907
 Reg. Book. 692 on the Wood, Iron or Steel Coaster of Raurimu Master Champion
 TONNAGE:- Built at Auckland By whom Dane & Brown When 1901
 GROSS 198 Owners Government of New Zealand Port belonging to Auckland
 UNDER DE. 164 Owners' Address Wellington
 NET 153 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Yes Name of Dock Auckland Destined Voyage South Seas

WB=CellDBorDBa feet; uE&B feet; f feet; f feet; f
 total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the ballast space.

Last Report, No. 262 Port Auckland

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes, and besides being detailed in the body of the report, should be summarized in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys
9.06
17/4/07
20/4/07
 Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Examination of Bottom
and to draw Tail shaft

Now Done. The Metal in the Bottom too good to strip off. Had a few patches put on where thin and the Bottom coated with copper paint.
 The Tail Shaft drawn and Stern tube rebushed. The Vessel is in good condition.

The Government Engineer Surveyor examined the Oil Engine and had a few minor Repairs, and passed the Vessel.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								<u>Tail shaft drawn</u>
Removed and Faired or Repaired								<u>Stern tube re-bushed</u>
Faired or Renewed in place								

PRESENT CONDITION OF THE

Decks <u>Good</u>	Stringers	Dbing. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Caulking of Decks <u>Do</u>	Inner Bottom Plating	Engine Room Skylights	When put on, Month <u>6</u> Year <u>1901</u>
Waterways <u>Do</u>	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Boats <u>Good</u>
Coamings <u>Do</u>	State if Tanks now tested	Scuppers	Masts, Yards, &c. <u>Do</u>
Beams & Fastenings <u>Do</u>	Bulkheads	Cargo Hatchways	Condition, how ascertained <u>Observation</u>
Outside Plating	Ceiling	Hatches	(State if wedges removed) <u>No</u>
Caulking of ditto	Cement or Asphalt (State which.)	Planking of Wood Vessels	Sails <u>Good</u>
Rivets	Rudder	Caulking ditto	Equipment letter
Breasthooks & Crutches	Windlass	Treenails ditto	Anchors, No. of <u>Complete</u>
Transoms	Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto	Cables (State if now ranged) <u>No</u>
Frames	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	" Rule length size
Floors		Ditto ditto at other places ditto	Hawsers & Warps <u>Complete</u>
Keelsons		Stringers, Clamps & Shells ditto	Standing & Running Rigging <u>Good</u>
		Salting (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,05," or "to remain as classed and to have record of survey, 1,05, and the notations of ss No. 1-05 and ptND05, &c."

In my opinion this vessel is eligible to remain as now classed in the Register Book without fresh record of Survey.

Survey Fee (per Section 25) £				Fees applied for, <u>April 1907</u>
Special Damage or Repair Fee (if any) (per Sec. 26) £	<u>3</u>	<u>3</u>		Received by me, <u>April 1907</u>
Travelling Expenses (if chargeable) £				
Second Surveyor's Fee (if any) £				

Committee's Minute

Character Assigned

FRI. 14 JUN 1907

QA-
Fitted with Aux Power
worked by oil engine

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation

W 941-0190