

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office. WED. 17 OCT. 1917.)

Date of writing Report 28 Sept. 19 17 When handed in at Local Office Glasgow 19 17 Port of Glasgow

No. in Reg. Book. 1170 Survey held at Glasgow Date, First Survey 28.8.14 Last Survey 28 Sept. 1917 (No. of Visits 7)

Tonnage { Gross 4779 Net 3041 Vessel built at Hartlepool By whom James Ritchie & Co When 1911

Registered Horse Power 448 Engines made at Hartlepool By whom Ridgway & Co When 1911

No. of Main Boilers 2 Boilers, when made (Main) 1911 (Donkey) 1915

No. of Donkey Boilers 1 Owners Captain James Ritchie & Co Port Glasgow Voyage Coastwise

Steam Pressure in Main Boilers 200 If Surveyed Afloat or in Dry Dock Grandby & Pinner St. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boilers 90

Last Report No. Port

Particulars of Examination and Repairs (if any) Damage Specializing +100 PSI

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.	Years and Months since last Survey.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>2.17</u>	<u>2.17</u>	<u>2.17</u>
<u>11.13</u>	<u>11.13</u>	<u>11.13</u>
<u>2.17</u>	<u>2.17</u>	<u>2.17</u>
<u>1.16</u>	<u>1.16</u>	<u>1.16</u>

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined. See copy attached

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " " " No - under steam.

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 205 lb.

Did the Surveyor examine the Safety Valves of Donkey Boiler? No To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes , and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers? Yes , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? Yes , and of the Donkey Boiler?

Was screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes or two liners? or is it without liners?

Was shaft now been changed? No If so, state reasons

Has the shaft now fitted new? Has it a continuous liner? or two liners? or is it without liners?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? Bottom now renewed.

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? The donkey boiler survey to be held in its entirety. This will be done at the first opportunity. Now done on account of damage - collision with S.S. SCINDIA on July 2nd 1917. Cylinders, piston, slide valves & faces, crank, thrust, stanchion shafts, pumps & condensers, examined & found in good order. Seven shaft, propeller, stern bush, sea connections and outside fastenings examined & found in good order. All auxiliary machinery overhauled. Condenser tubes drawn, cleaned, condenser repacked and tested. Some tubes & ferrules renewed. Dynamo engine overhauled. Armature of old magnets rewound, all wiring in 2nd & 3rd spaces renewed and wiring throughout vessel renewed and repaired as necessary.

Special survey: Main Boilers examined throughout and found in good order. After CE stay renewed. Main steam pipe annularly & tested to 200 lb. water pressure. Steering engine & rudderlass examined. Earthquake motion arrangement examined. This machinery

General Observations, Opinion, and Recommendation: -

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9, 11, B.&M.S. 9, 11, or S.L.M. 9, 11, 140 lb., P.D., &c.

is eligible in my opinion to remain as classed with the notation + L.M.C. 9.17 when the survey is completed. Note seven shaft seen 9.17.

Survey Fee (per Section 28) £5 10 0 Fees applied for 6/10/1917

Special Damage or Repair Fee (if any) (per Section 28.) £5 5 0

Travelling Expenses (if chargeable) £

Received by me, B. Ritchie 19/10/17 28/10/17

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute GLASGOW, 16 OCT. 1917

Assigned As now. Note shaft. Note 7th L.M.C.

ms 9.17

W 953-0105

Insert Character of Ship and Machinery precisely as in the Register Book.

In a Certificate required? If so, to be sent to



LS No 3 due 11.17. held as per
Bd due 2.18 partly held to be
Completed 18th opportunity.

Machinery named for Collision Damage

It is submitted that
this vessel is eligible for
THE RECORD. + LMC MS 9.17
59.14.

It is submitted that this
vessel WILL BE eligible
for the record. + LMC 9.17
When the RDB has been
held.

V.S.
18.10.17.

N.B. - If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register
Foundation