

FRI SEP 6-1912

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report 16<sup>th</sup> August 1912. When handed in at Local Office 16<sup>th</sup> August 1912. Port of YOKOHAMA.

To. in Book. Survey held at YOKOHAMA.

Date, First Survey 2<sup>nd</sup> August Last Survey 16<sup>th</sup> August 1912

FRI SEP 6-1912

17 on the Machinery of the Wood, Iron or Steel s.s. "Dacre Castle" Master E. Gough  
 Gross 4261 (No. of Visits 6)  
 Net 2653  
 Registered 459  
 Horse Power 1  
 of Main Boilers 2  
 of Donkey Boilers 1  
 Steam Pressure 180 lbs.  
 Main Boilers 180 lbs.  
 Donkey Boilers 100 lbs.  
 Vessel built at Middlesbrough By whom R. Craggs & Sons Ltd. When 1908. 2  
 Engines made at Stockton By whom Blair & Co. When 1905  
 Boilers, when made (Main) 1908 (Donkey) 1908  
 Owners Lancashire Shipping Co. Ltd. Port Liverpool Voyage New York  
 If Surveyed Afloat or in Dry Dock Yokohama No. 3  
 (State name of Dock.)

Last Survey No. Port

Particulars of Examination and Repairs (if any). Damage through grounding.

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of damage (the cause of which must be stated) should be separated from Repairs due to other causes; and repairs being detailed in the body of the report, should be briefly summarised at the end of the report. State also the date and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ✓ also whether any damage report was made, and, if so, by whom? Yes by undersigned.

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

Do. " Donkey " "

This was not done, state for what reasons? ✓

What parts of the Boilers could not be thus thoroughly examined? ✓

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ , and of the Donkey Boiler? ✓

the Surveyor examine the drain plugs of the Main Boilers? ✓ , and of the Donkey Boiler? ✓

the Surveyor examine all the mountings of the Main Boilers? ✓ , and of the Donkey Boiler? ✓

Is screw shaft now been drawn and examined? Yes. Is it fitted with continuous liner? Yes. or two liners? ✓ or is it without liners? ✓

Is shaft now been changed? No. If so, state reasons ✓

Is the shaft now fitted new? ✓ Has it a continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

Is the distance between lignum vitae of stern bush and top of after bearing of screw shaft? New lignum vitae fitted.

The Survey is not complete state what arrangements have been made for its completion and what remains to be done? ✓

Propeller blades (bronze) fair'd and dressed up. Propeller shaft drawn and found in good condition, lignum vitae renewed, and line of shafting tested. Condenser tubes drawn, the condenser cleaned, and afterwards tested. Guide plates and shoes planed and refitted. Crank pin brasses of fan engine remetalled. L.P. eccentric strap remetalled, and trough for H.P. eccentric straps renewed. Thrust collars faced up and relined. Three electric cables renewed. Oil pipes & cups for pump link brasses renewed. One bilge strum renewed. Water service pipes to guides repaired. Main steam pipes annealed and tested by hydraulic pressure to 360 lbs. per sq. in. New propeller blades to be fitted at Owners' convenience.

## Summary of Damage Repairs

Removed: - Lignum vitae. White metal of fan engine crank pin brasses & L.P. eccentric strap. Trough for H.P. eccentrics. Three electric cables. Oil pipes & cups for pump link brasses. One bilge strum. over

General Observations, Opinion, and Recommendation: - The machinery of this vessel is now in good order and safe working condition, and is, in my opinion, eligible to remain as classed with the notation of "Tail shaft seen 8.12"; the four propeller blades being renewed at owners' convenience on account of loss of surface.

Survey Fee (per Section 28) £ 4/-

Fees applied for

16<sup>th</sup> Aug 1912

a.s.w.

Special Damage or Repair Fee (if any) £ 50/-

Yen 50/-

Received by me,

20 Aug 1912

Traveling Expenses (if chargeable) £ 0/-

a.s. Williamson  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

TUE SEP 10 1912

Signed

As above.

W959-0056



© 2020

Lloyd's Register  
Foundation

Grounding damage  
Screw shaft & part machinery

examined & replace effected  
new propelle blades are to be  
fitted at Owner's convenience  
it is submitted that  
vessel is eligible to  
remain as CLAS&D.

S8.12

EF  
6.9.14

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

overhauled and repaired :— Propeller blades. Shafting. Condenser. Guide plates and

shoes, Thrust collars, Water service pipes, Main steam pipes.

REPAIRS

\* THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register  
Foundation