

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 38974

SAI.-2.SEP.1916

(Received at London Office

Report of Survey for Repairs, &c., of Engines and Boilers.

Survey held at Cardiff Date, First Survey 16 Aug. Last Survey 26 Aug. 1916

on the Machinery of the Wood, Iron or Steel Sc. Sr. Bayhall Master

Age Gross 3898 Net 2524 Vessel built at Newcastle By whom R. Stephenson & Co. Ltd When 1906 1

Engines made at " By whom R. E. Mac. E. & Co. Ltd When 1906

Boilers, when made (Main) 1906 (Donkey) 1906

Owners The Bay S. S. Co. Ltd Port London Voyage

Surveyed Afloat or in Dry Dock Channel

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.

Machinery and Boiler Surveys (including date of N.B., if any).

100 A1

Spartan with ftd

3.16

S.S. Pot. 8.2.13

L.M.C.

A.S. 11.13

B.S. 10.15

J.S. 3.16

Was a damage report made by anyone else? If so, by whom?

The Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey " " "

Was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

The Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

The Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

The Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boiler?

The Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

The Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes or two liners? or is it without liners?

shaft now been changed? No If so, state reasons

shaft now fitted new? Has it a continuous liner? or two liners? or is it without liners?

the distance between lignum vitae of stern bush and top of after bearing of screw shaft? Lower half of bush rewooded

Survey is not complete state what arrangements have been made for its completion and what remains to be done? Survey complete.

Examined intermediate pressure slide valve and cylinder face.

Low pressure cyl. and piston and rod. Low press slide valve.

top ends of all connecting rods, crank, thrust and screw shaft.

propeller, stern bush, sea cocks and valves, and their fastenings

bilge injection valve, condenser, feed and bilge pumps and

valves, auxiliaries, pipes, steering eng, windlass and screw

stays in main boilers and found or made good as under

Intermediate pressure slide valve taken to works, and face dressed

and back lined up. The cyl. face also dressed in place, and at some

more favourable opportunity, a false face and new valve will be

fitted, meantime these are in safe working condition

New end fitted to slide valve spindle, neck and gland bushes

General Observations, Opinion, and Recommendation:--The machinery of this vessel

state clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also

any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 2, 11, B.M.S. 2, 11, or L.M.C. 2, 11,

140 lb., F.D., &c.)

as far as seen is in good condition and eligible in my

opinion to remain as classed, and to have record of survey

J.S. 8.16 in the Register Book

Survey Fee (per Section 28) £

Damage or Repair Fee (if any) £ 6.6.

Selling Expenses (if chargeable) £

Fees applied for 12. Sept. 1916.

Received by me, 4. 9. 1916

James Barclay

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI.-8.SEP.1916

signed (without spl. condn)

FRI. 5.-JAN. 1917

Lloyd's Register

Foundation

W 961-5592 1/2



Machinery generally sound  
& repairs effected

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that  
this vessel is eligible to  
remain as **CLASSED**.

Without restrictions.

Sp. 16

W.S.  
5.9.16



© 2020  
Lloyd's Register  
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



Port of **CARDIFF**

Continuation of Report No. 38974 dated August 1916 on the

Sc. Sr. Bayhall

bushes made to fit.

Low pressure piston rod examined, and found in safe working condition, guides and shoes lined up

New end fitted to low pressure slide valve spindle, and neck and gland bushes made to fit.

Crown brass of top end of Int. press. connecting rod renewed.

Top ends of high and low pressure connecting rods examined, there are slight surface cracks in brasses, which do not affect efficiency or safe working.

Low press. connecting rod, bottom end re-metalled.

The metal in top halves of main bearings is in good order

Thrust shaft put in lathe, collars trued up, shaft refitted shoes re-metalled and refitted.

Intermediate stop valve renewed.

Screw shaft key refitted.

Lower half of stern bush rewooded, and patch fitted to face of stern gland.

Condenser tubes drawn, cleaned, replaced, and repacked. Condensers tested.

Bilge pumps, port and starboard suction valve boxes renewed.

Auxiliary feed pump renewed.

Donkey boiler feed pump overhauled put in order.

Ballast pump overhauled, slide valve spindle renewed bucket refitted, stop valve and spindle renewed.

pump tried and found good.

All pipes bilge and tank overhauled, repaired &amp; partly renewed.

Steering engine overhauled. worm wheel and crank shaft renewed.

Windlass overhauled. Cable lifters renewed.

Main boilers cleaned and scaled, the screw stays will be attended to when vessel goes through boiler survey in October. meantime they are in safe working condition.

Donkey boiler plain tubes renewed, and smoke box and uptake repaired.

James Barclay



© 2020

Lloyd's Register  
Foundation

W961-0092 2/2