

Port of Bilbao


20th June 1902

German de Bareris
assisted by C de Torres marine engineer

Sydney T. Dyer Esq - Lloyd's
Agent here, hold a survey aboard the
steamer Ballesteros N^o 3 of Aviles 171
tons gross, when she was placed in dry
dock on the 3rd inst and subsequent
days, for the purpose of ascertaining
the damages sustained through ground-
ing on the 28th May last near Freja-
jada (north coast of Spain) while on
her voyage from Villagarcia to this port.
(Particulars of which are stated on the
Captain's protest)

Damages = Flat Keel plate N^o 1. =
Port side, B Strake N^o 1 counting from
the stern = C Strake N^o 1 & 2. = Starboard
side B Strake N^o 1, 4, 5. = seven shell
plates broken or defective. The stern
slightly bent towards port side from
two to four feet water line; the flat
keel plate N^o 5. = Port side B Strake N^o 3, 5, 6, 7,

© 2021




Lloyd's Register
Foundation

W 62-5150 1/3

C Stake N^o 6, 7. = D Stake N^o 1 & 2. = Starboard side A Stake N^o 4 & 7. = C Stake N^o 1 = twelve plates more or less indented, the frames N^o 1, 2 & 3 of port side badly bent; three floors & reversed bars at fore peak also bent; one keelson angle bar bent at fore end; one length of bilge keel bulb plate on each side buckled and a few rivets started; cement broken in many places damaged; the caulking of fore castle and poop wood decks started.

Machinery: The four propeller blades broken away; H.P. piston rod scored; H.P. Slide valve & face scored; crank shaft after journal started; Trust shoes cracked; H.P. piston packing rings defective; H.P. & L.P. valve spindles scored; two lead bilge pipes broken; Doulton pumps damaged; sea wells & valves started.

Recommended: That the stern be cut loose and fairied in place; the broken shell plates to be renewed; the indented plates B N^o 5 & 6 = D N^o 1 of port side, A N^o 4 & 7 = C N^o 1 of starboard side, then six plates to be removed, fairied & refitted, the keel plate N^o 5 = B. N^o 3 & 7 = C. N^o 6, 7 = D N^o 2 of port side, then six plates to be removed & refitted.



© 2021

Lloyd's Register
Foundation

The three damaged frames be renewed; the three floor plates renewed, fairied & refitted; two rudder bars be renewed and one fairied & refitted; the Karlson angle bar be fairied in place; the bridge deck bulk plates also fairied in place & started rivets renewed; the consent be cut clean and renewed along this damage; the fore castle and poop deck to be caulked & payed; a great part of close ceiling in hold to be removed to allow of this repairs being effected; the fore peall trunk to be tested on completion of repairs and bottom cleaned & painted.

Machinery: The propeller to be renewed, H.P. piston rod. to be skinned in latter & new bushes, - H.P. slide valve & face to be refaced & trued up, - Crank shaft after journal to be renewed & trued up in latter, - Trust shoes to be overhauled, - H.P. piston packing rings to be renewed, - H.P. & L.P. valve spiritless be trued up in latter, - two lead pipes to be repaired, - Donkey pump also repaired. - Sea cocks & valves to be overhauled and shafting relined all fore and aft.

I delivered the present Certificate to the owners of this vessel to serve the interest of all them whom it may concern.

Los del *San Juan*
Erasmus

John Parson

Office fees of Surveyor to Lloyd's Register
Sursey 10/10/0
L N 210

