

Bpt. 8.

(Received at London Office TUE 9 APR 1918 No. 70822)

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report	March 1918	When handed in at Local Office	Port of
No. in Reg. Book.	Survey held at	Blyth	Date, First Survey
(221) on the Wood, Iron or Steel	9s "Archbank"	(No. of Plots)	Last Survey
TONNAGE:-	Built at West Hartlepool	Master	1905
ROSS 3764	By whom Yarrows Blyth & Co	YEAR	6
UNDER DR. 3572	Owners Sutherland & Co Ltd (A. M. Sutherland Mgr.)	MONT.	
ET 2453	Port belonging to Newcastle		
Owners' Address ✓			
Surveyed Afloat or in Dry Dock? Name of Dock			
B=Cell DB or DBa feet; uE&B feet; f feet; f feet; t tons.			
al capacity tons. FPT tons; APT tons; MT feet tons.			

N.B. - All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, etc., and of the inner bottom plating, especially in the boiler space.

First Report, No. 927 Port Blyth

Technical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; a besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the date and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).		
CHARACTER.	Yards Anchored now extant.	Machinery and Boiler Survey (including date of N.B., if any).
H 100 A.1. Spank with plate. 1.1Y		Hull 6.14 B.S. 1.14
Lshuc W2-14		Y.S. 10.14

image cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Yes: not required

Was a damage report made by anyone else? If so, by whom? A. B. Coull & Co

AIRS, OR EXAMINATION AS PER RULE, FOR Damage & Special Examination

Damage stated to be due to Collision. cu. Malta report to 927

at side sheer strake. 1/6 plate renewed. w 5' fair in place.

1/4 below sheer strake w 5' plate renewed.

names: 3 cropped and fair in place.

upper plates: 1 plate renewed and 2 fair in place. (cu. deck plate fair in place)

length of gunwale bar renewed. 1 removed fair and replaced. and 1 fair in place.

Tulwark plates renewed and 2 fair in place: 2 lengths of rail bar renewed

" stanchions renewed. and 3 removed fair and replaced.

wash port doors renewed. 16 stanchion lugs renewed

Beams cropped and fair in place. 2 fair in place. 3 knees fair and refitted

ART OF DAMAGE REPAIRS:-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed	2				✓	1	✓	2 bulwark plates and 4 stanchions Renewed
Removed and Fairied or Repaired	✓	3			2	✓	✓	
Fairied or Repaired in place	2	2			2	2	✓	

ART CONDITION OF THE GOOD	Stringers	At Gramd Good	Dblng. Plates under sounding Pipes	✓	Copper, or Y.M. of Wood Vessels
of Decks	Inner Bottom Plating	✓	Engine Room Skylights	Good	(State if iron bolt.) When put on, Month Year
of	State if Tanks have been examined inside	At Gramd	Coal Bunkers, Openings, Lids, &c.	—	Boats
yes	State if Tanks now tested	✓	Scuppers	—	Good
is	Bulkheads	Good	Cargo Hatchways	—	Mask, Yards, &c.
Fastenings	Ceiling	—	Hatches	—	Condition, how ascertained from the (State if wedges removed)
Plating	Cement or Asphalt	✓	Planking of Wood Vessels	—	to
of ditte	Rudder	At Gramd Good	Caulking	ditto	Equipment letter
locks & Crutches	Steering gear and its connections	Good	Treecails	ditto	Anchors, No. of
Frames	Windlass	—	Breastbeaks & Stemson	ditto	Cables (State if now ranged)
is	Have Pumps now been examined and found efficient?	no	Transoms, Painters, & Cratches	ditto	length (on board) size
is	Have Sluice Valves now been examined and found efficient?	✓	Timbers of Frame at openings	ditto	“ Rule length size
is	Have Watertight Deers new been examined and found efficient?	no	Ditte ditte at other places	ditto	Stated Complete
is			Stringers, Clamps & Shells	ditto	Hawser & Warps
is			Salting	ditto	Standing & Running Rigging
is			(State if examined.)		

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss. 1-15 and p. 15, &c."

This vessel is eligible in my opinion to remain as classed and to have the notation of examined 3, 18 made in the Register Book subject to the Boiler room tank not being used until repaired and the damage to the Port bow being made good at the first favourable opportunity.

Survey Fee (see Section 28) £ 5 : 5 0
Special Damage or Repair Fee (if any) per Sec. 29 £ 5 : 5 0
Travelling Expenses (if chargeable) £ 2 : 0 : 0
Second Surveyor's Fee (if any) £ 2 : 0 : 0

Fees applied for,

Received by me,

13.5.18 E.C.

14.5.18

TUE. 16 APR. 1918

Surgeon to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

Deferred for No 3
but record,
Examined 3-18

B. J. 3-18



Lloyd's Register
Foundation

SS Archbank
Special Examination.

The decks, holds, fore peak, bridge space, machinery space, port bow bunkers, doops, coamings, casings, hatchways & hatches, masts, spars & rigging, windlass, steering gear & general equipment examined. The boiler room tank examined internally: the tank top under the boilers and also the floors throughout are good, but it was found that the tank top under the stokehole floor was holed; a bolted doubling has been fitted here and the tank cut off from the ballast line.

The vessel generally is in good sufficient condition for repair.

One doubling plate fitted to boiler casing on bridge deck and No 1 hatch webs repaired.

The temporary repairs on the port bow are sufficient and permanent repairs could not be sanctioned at this time.

John Currie



©2021
Lloyd's Register
Foundation