

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

AUG -5 1939

Date of writing Report 1<sup>st</sup> Aug 1939, When handed in at Local Office 1<sup>st</sup> Aug 1939 Port of CARDIFF  
 No. in Reg. Book 78037 Survey held at Cardiff Date, First Survey 1<sup>st</sup> July Last Survey 29<sup>th</sup> July 1939  
 Tonnage { Gross 5334 Net 3415 Vessel built at Port Glasgow By whom Wm Hamilton & Co Ltd When 1918-7  
 Nominal Horse Power 476 Engines made at Guelph By whom J. G. Kuicaid & Co Ltd When 1918  
 No. of Main Boilers 2 Boilers, when made (Main) 1918 (Donkey) 1934  
 No. of Donkey Boilers 1 Owners Jugoslavanska Plovidba D.D. Owners' Address (if not already recorded in Appendix to Register Book.)  
 Steam Pressure in Main Boilers 180 lbs Managers Port Susak Voyage   
 in Donkey Boilers 100 lbs If Surveyed Afloat & in Dry Dock Mount Stuart Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No.  Port Particulars of Examination and Repairs (if any) M.S. Compl. B.S. T.S.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No" " Donkey " " " NoIf this was not done, state for what reasons? Boilers previously examined at Cardiff. see Off Rpt 52846.And what parts of the Boilers could not be thus thoroughly examined? ✓Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓State latest date of internal examination of each boiler ✓Present condition of funnel ✓ goodDid the Surveyor examine the Safety Valves of the Main Boiler? ✓To what pressure were they afterwards adjusted under steam? ✓Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓To what pressure were they afterwards adjusted under steam? ✓Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓, and of the Donkey Boilers? ✓Did the Surveyor examine the drain plugs of the Main Boilers? ✓, and of the Donkey Boilers? ✓Did the Surveyor examine all the mountings of the Main Boilers? ✓, and of the Donkey Boilers? ✓Has screw shaft now been drawn and examined? yes Is it fitted with continuous liner? yesIs an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓Has shaft now been changed? No If so, state reasons ✓Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓State date of examination of Screw Shaft 6-7-39 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 5/32"

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light yes fitted? yesIf so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? yesHas the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? yesIf the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Now done:- Vessel placed in dry dock. propeller, stern bush and sea connection fastenings examined. Sea Cocks & Valves opened out & examined. Propeller shaft drawn in and examined.

Examined Cylinders, pistons, Slide Valves, Crank, Thrust & intermediate Shafting and bearings, pumps, Condenser (tested) Auxiliaries & pumping arrangements

Steam pipes over 3" tested to 360 lbs / sq" hydraulic pressure. pipes removed for test.

Electric light installation examined and Megger tested. Dynamo engine tried under working conditions Governor tested. Windlass & Steering Engine examined.

A new feed water heater has now been fitted Marked 1107ds N° N270 DRW. 27-4-39. all pipes & fittings tested as required by the Rules.

General Observations, Opinion, and Recommendation:- The Machinery of this vessel is

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, B.&M.S. 9.11, & L.M.C. 9.11, or L.M.C. 140 lb., F.D., &c.)

eligible in my opinion to remain as classed and have record of +LMC M.S. 7.39  
 mutation of T.S. CL 7-39. and B.S. 3.39 as previously recommended.

Survey Fee (per Section 29) MS £ 9 : 0 : 0

Special Damage or Repair Fee (if any) £ 1 : 0 : 0

Feed water heater £ 2 : 2 : 0

Travelling expenses (if chargeable) £ : : :

Fees applied for

1<sup>st</sup> Aug 1939

Received by me,

12 8 1939

Committee's Minute


FRI 25 AUG 1939

Assigned

+ LMC: MS 7.39

BS 3.39

Hamilton W & Paton  
 Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register  
 Foundation

W982-0276 1/2



S.S. "Labud"

Coupl. B.S. One stay tube in port main boiler renewed.

Repairs:- After main engine feed pump race renewed.

Weir feed pumps. S & D Valves & seats machined, bucket rings renewed, for<sup>d</sup> pump bucket rod renewed.

Dynamo engine. Valve spindle renewed, piston rings renewed.

Fan engine:- Cylinder & Valve chamber bored out; new piston & Slide Valve fitted, Valve spindle renewed. Piston rod skinned.

Electric Installation. Fore main main part renewed, Saloon circuits through bunkers renewed, new junction boxes fitted in bunkers.

Engineers Accommodation, Feeds for skin side from Messroom renewed.

Engine room, Two lights & one plug rewired. Tunnel fire lights renewed.

J. J. Jones



© 2020

Lloyd's Register  
Foundation



It is submitted that  
this vessel is eligible for  
THE RECORD.

Mum  
 23. 8. 39

human was found but injured in all - injured  
 body, human also with a r. injured but still  
 human was injured. found of human first  
 human first injured, human found with injured  
 body but injured was human injured with injured  
 human found injured. human found with injured  
 human found with injured of body. injured  
 human found with injured. human found with injured

"burbot" 220  
Dumplings served warm with butter and 20.00

*hibos.*